Crew Behavior Monitoring Report

Generated: 2026-04-14 11:08:03 | File: WhatsApp Video 2026-01-19 at 2.01.25 PM 1.mp4 | Duration: 282s | Frames Analyzed: 77

#1 Crew Alertness

Status: HIGH

High. Crew members remained alert, maintaining upright posture and active engagement.

Confidence: HIGH

#2 Crew Distraction

Status: MODERATE

Moderate. A crew member occasionally turned their head away from the forward view, indicating some level of divided attention.

Confidence: HIGH



#3 Crew Doing Writing Work

Status: NOT_OBSERVED

Not Observed. No writing materials were detected and no crew member was seen doing writing work.

Confidence: HIGH

#4 Crew Taking Nap / Micro-sleep

Status: NOT_OBSERVED

Not Observed. No significant evidence of napping or prolonged eye closure was seen.

Confidence: HIGH

#5 Crew Using Mobile

Status: OBSERVED

Observed. A crew member was seen actively using or holding a mobile phone during the monitored period.

Confidence: HIGH

Crew Behavior Monitoring Report

Generated: 2026-04-14 11:08:03 | File: WhatsApp Video 2026-01-19 at 2.01.25 PM 1.mp4 | Duration: 282s | Frames Analyzed: 77



#6 Crew Packing Belongings

Status: NOT_OBSERVED

Not Observed. Bags or belongings were detected in the cab, but they appear to be stationary.

Confidence: LOW

#7 Crew Leaving Place

Status: NOT_OBSERVED

Not Observed. Both crew members remained in their designated seats or expected operational areas.

Confidence: HIGH

#8 Crew Operating Horn Lever/Switch

Status: OBSERVED

Horn lever active detected by custom YOLO in 7/77 frames (3 consecutive). Strong evidence of horn operation.

Confidence: HIGH



Crew Behavior Monitoring Report

Generated: 2026-04-14 11:08:03 | File: WhatsApp Video 2026-01-19 at 2.01.25 PM 1.mp4 | Duration: 282s | Frames Analyzed: 77

#9 LP Applying A9/SA9 After Halt

Status: NOT_OBSERVED

No A9/SA9 brake application detected by custom YOLO in any frame.

Confidence: HIGH

Overall Safety Assessment

Analysis flagged 2 concern(s): mobile phone usage, horn lever operation detected.

Recommendations

- Enforce no-phone policy during locomotive operation.
- Horn lever operation detected. Verify appropriate horn usage per operating rules.