3.032 Mechanical Behavior of Materials

Fall 2007

Image removed due to copyright restrictions.

Please see http://www.bostonroads.com/crossings/tobin/img2.jpg

3.032 Mechanical Behavior of Materials

Fall 2007

Force distributions in structures

Expand stent structure under balloon expansion

Force on metal strut due to this loading?




Image removed due to copyright restrictions.

Please see

http://www.nhlbi.nih.gov/health/dci/images/stent_lowres.gif

http://www.abbottvascular.com/en_US/content/image/acculink1_lg.jpg