Ex.No.-1.2 DESIGN AND DRAFT THE GIVEN 2D SKETCHES IN MODELLING SOFTWARE

Date: 11-10-2026

AIM

To sketch the given drawing with dimensions using the Autodesk Fusion 360 tool.


REQUIREMENTS

1. Autodesk Fusion 360
2. Windows 10
3. 16 GB of RAM (integrated graphics recommended 1 GB or more)
4. 2.5 Mbps or faster download; 500 Kbps or faster upload

PROCEDURE


1. Open a new file and then select the Sketch icon.
2. Select the plane for sketching.
3. Use the sketching features under the CREATE menu (Line, Circle, Arc, Rectangle, Polygon, etc.) to draw the given sketch.
4. Use the sketch modifying features under the MODIFY menu (Fillet, Trim, Extend, Offset, Move/Copy, Mirror, etc.) to edit the sketch.
5. Use the Inspect > Measure feature to check the dimensions of the sketch.
6. After finishing the sketch, use the Finish Sketch option to finalize the sketch.
7. After finishing the sketch, switch to Drawing mode (Design > Drawing > From Design) to plot the sketch in ISO standard.
8. In the Create Drawing dialog box, set Contents: Full Assembly, Drawing: Create New, Template: From Scratch, Standard: ISO, Units: mm and Sheet Size: A3 (420 mm x 297 mm), then click OK.

SKETCH



Given 2D sketch with dimensions

OUTPUT



Drafted 2D sketch in ISO standard (A3 sheet) with top, front and side views

RESULT

Thus, the given sketch is drawn and drafted using Fusion 360 tool.