Ex.No.-1.2 DESIGN AND DRAFT THE GIVEN 2D SKETCHES IN MODELLING SOFTWARE

Date: 11-10-2026

AIM


To sketch the given drawing with dimensions using the Autodesk Fusion 360 tool.

REQUIREMENTS

1. Autodesk Fusion 360
2. Windows 10
3. 16 GB of RAM (integrated graphics recommended 1 GB or more)
4. 2.5 Mbps or faster download; 500 Kbps or faster upload


PROCEDURE

1. Open a new file and then select the Sketch icon.
2. Select the plane for sketching.
3. Use the sketching features (Line, Circle, Arc, Rectangle, Polygon, etc.) from the Create menu to draw the given sketch.



Sketch > Create menu

4. Use the sketch modifying features (Fillet, Trim, Mirror, Move/Copy, Offset, etc.) from the Modify menu to edit the sketch.




Sketch > Modify menu

5. Use the Inspect feature (Measure) to check the dimensions of the sketch.



Inspect > Measure

6. After finishing the sketch, use the Finish Sketch option to finalize the sketch.




Finish Sketch

7. After finishing the sketch, switch to Drawing mode (Drawing > From Design) to plot the sketch in ISO standard.




Switching to Drawing mode

8. In the Create Drawing dialog box, set Contents to Full Assembly, Drawing to Create New, Template to From Scratch, Standard to ISO, Units to mm and Sheet Size to A3 (420 mm x 297 mm), then click OK.




Create Drawing dialog box

SKETCH



Given sketch with dimensions

OUTPUT



Drafted sheet (ISO, A3) with front, top and side views

RESULT

Thus, the given sketch is drawn and drafted using the Fusion 360 tool.