NET MANAGER SECURE 1.1.1 RELEASE NOTES

Silver Spring Networks
230 West Tasman Drive
San Jose, CA 95134
www.silverspringnet.com

Confidential Information of Silver Spring Networks®, Inc., provided under nondisclosure obligations.

Copyright © 2016 Silver Spring Networks, Inc. All rights reserved.

The following are registered trademarks of Silver Spring Networks, Inc: the Silver Spring Networks name and logo, Altogether Brilliant®, Connect to the Energy Network®, CustomerIQ®, GreenBox®, GridScape®, Micromesh®, Power Over Energy®, Silver Spring®, Silver Spring Networks (and design)®, UtilityIQ®, UtilOS®.

The following are trademarks of Silver Spring Networks, Inc: Connect to The Everything Network™, EnergyIQ™, Gen™, GreenIQ™, MicroAP™, Milli™, NetworkIQ™, OpsIQ™, Rings Logo™, SensorIQ™, SilverLink™, Streetlight.Vision™, The Internet of Important Things™.

All other company and product names are used for identification purposes only and may be registered trademarks, trademarks, or service marks of their respective owners.

Please consider the environment before printing this document.

Revisions

Number	Date	Revision
1	Feb 2016	Added version 1.1.1.

Contact us. Email **techpubs@silverspringnet.com** with suggestions or corrections for this or any document.

Customer Support

Telephone	Hours	Email
Toll free within the US and Canada: 1-888-SSN-9876 (1-888-776-9876) Non-toll-free: 1-669-770-4298	5:00 AM - 6:00 PM US Pacific Time	**support@silverspringnet.com**
In Australia: 1300 706 769	9:00 AM - 9:00 PM Australia Eastern Time	**aus-support@silverspringnet.com**
Contact us on the Web: http://www.silverspringnet.com/services/customer-support/		

Contents

Net Manager Secure 1.1.1 Release Notes 4
Who Should Upgrade 4
Resolved Issues 4

NET MANAGER SECURE 1.1.1 RELEASE NOTES

Release Date: 26 February 2016

This document contains information about Net Manager Secure version 1.1.1.

Who Should Upgrade

This release of Net Manager Secure fixes issues related to security association. Customers should upgrade to Net Manager 1.1.1 to fix these issues.

Resolved Issues

The following issues were resolved in version 1.1.1:

1. net_mgrS security association lifetime is too long (NETMGRS-7)

net_mgrS created security associations that were 45 days long. This was a security issue. This issue was fixed. The default security association is now 5 days with --salifetime as a new optional that takes a time interval and truncates it to the nearest 5 minute interval.

2. Bug in net_mgrS: "Too many concurrent applications" (NETMGRS-8)

net_mgrS only closed its connections to HSMs correctly if it was stopped via SIGQUIT, it did not close connections properly in a normal exit. As a result, if net_mgrS was run successfully more than 256 times in a row, in less than 5 minutes an error occurred. The error encountered in the failure mode was an error from the HSM, which affected other applications if they tried to connect to the HSM after net_mgrS triggered the failure. This issue was fixed.

3. Add security association timeouts to net_mgrS (NETMGRS-9)

Users could not modify the timeouts used in the security association negotiation phase. This issue was fixed. Instead of setting a timeout for the whole command, users can now separate the timeouts for secure association phase vs the actual command. `-t` is passed to association commands, unless `--satimeout` is passed in which case it is used instead of the `-t` value.