

Quadrature (Q)
2
0
−2
−4
−6
−7
−6
−5
−4
−3
−2
In-Phase (I)
|0⟩ cloud
|1⟩ cloud
leakage
decision boundary
relaxation |1⟩→|0⟩
excitation |0⟩→|1⟩
near-boundary
state-prep error