

Promise[®] SmartStor DS4600 SR1 Compatibility List V1.6

Date: 08/30/2013

Document History:

- **V1.0:** 1. First release (Based on the original verification, SR1 FW/SW had a little bit minor changes)
2. Based on the original Compatibility List , added some new devices as below
 - ◆ Host Systems: 2Q'ty
 - ◆ SATA Hard Drives: 10Q'ty
 - ◆ Operating System: 3Q'ty
- **V1.1:** Add some new devices.
- **V1.2:** Add some new devices. (Highlighted them with blue-color)
- **V1.3:** Add e.SATA HBA 3Q'ty for MAC OS x
- **V1.4:** Add SATA 3TB Drive 2Q'ty
- **V1.5:** Add some new devices.
- **V1.6:** Add some new devices.

Compatibility list included versions in this build are:

Firmware: 2.08.0000**SmartNAVI Utility: 1.6.0.21**

DEVICE COMPATIBILITY NOTE:

Basic compatibility between the 3rd party device and Promise device has been verified in typical configurations, Unless otherwise stated.

The EOL of 3rd party device may not be in the current list, user can refer older version of Promise compatibility list to get those test result.

DISCLAIMERS:

Only the versions available at time of testing have been verified, as listed.

Corner cases may exist depending on user configuration etc.

Individual 3rd party units may exhibit problems that did not show up in through the Promise test process.

Published

Performance is not assured with configuration deviations.

Some listed devices may go EOL. AVL listing does not imply market availability.

1. SATA Hard Drives

Vendor	Family	Model	Capacity	Firmware	Transfer-Rate	Buffer	Form Factor	NCQ/TCQ
HITACHI	Ultrastar A7K2000	HUA722020ALA330	2TB	JKAOA20N	3.0Gbps	32MB	3.5"	NCQ
	UltraStar A7K1000	HUA721075KLA330	750GB	GK8OA70M	3.0Gbps	32MB	3.5"	NCQ
		HUA721050KLA330	500GB	GK6OAB0A	3.0Gbps	16MB	3.5"	NCQ
		HUA721010KLA330	1TB	GKAOAB0A	3.0Gbps	32MB	3.5"	NCQ
	Deskstar 7K2000	HDS722020ALA330	2TB	JKAOA28A	3.0Gbps	32MB	3.5"	NCQ
	Deskstar 7K1000.C	HDS721010CLA332	1TB	JP40A39C	3.0Gbps	32MB	3.5"	NCQ
	Deskstar E7K1000	HDE721010SLA330	1TB	ST6OA31B	3.0Gbps	32MB	3.5"	NCQ
		HDE721050SLA330	500GB	ST3OA31B	3.0Gbps	32MB	3.5"	NCQ
	Deskstar 7K1000.B	HDT721010SLA360	1TB	ST6OA31B	3.0Gbps	16MB	3.5"	NCQ
		HDT721064SLA360	640GB	STDOA31B	3.0Gbps	16MB	3.5"	NCQ
		HDT721032SLA360	320GB	ST2OA31B	3.0Gbps	16MB	3.5"	NCQ
	Deskstar 7K1000	HDS721010KLA330	1TB	GKAOA70M	3.0Gbps	32MB	3.5"	NCQ
	Deskstar P7K500	HDP725050GLA360	500GB	GM4OA52A	3.0Gbps	16MB	3.5"	NCQ
		HDP725032GLA360	320GB	GM3OA52A	3.0Gbps	16MB	3.5"	NCQ
		HDT725050VLA360	500GB	V56OA52A	3.0Gbps	16MB	3.5"	NCQ
		HDT725040VLA360	400GB	V5COA7EA	3.0Gbps	16MB	3.5"	NCQ
	CinemaStar P7K1000.B	HCT721010SLA360	1TB	ST6OA31E	3.0Gbps	16MB	3.5"	NCQ
	CinemaStar P7K1000	HCS721010KLA330	1TB	GKAOAB0A	3.0Gbps	32MB	3.5"	NCQ
	CinemaStar P7K500	HCP725025GLA380	250GB	P21OABEA	3.0Gbps	8MB	3.5"	NCQ
		HCP725016GLA380	160GB	GMBOA5CA	3.0Gbps	8MB	3.5"	NCQ
	Deskstar™ 7K3000	HDS723030ALA640	3TB	MKAOA5C0	6.0Gbps	64MB	3.5"	NCQ
MAXTOR	DiamondMax 23	STM31000528AS	1TB	CC35	3.0Gbps	32MB	3.5"	NCQ
		STM3750528AS	750GB	CC34	3.0Gbps	32MB	3.5"	NCQ
		STM3500418AS	500GB	CC34	3.0Gbps	16MB	3.5"	NCQ
		STM3250318AS	250GB	CC44	3.0Gbps	8MB	3.5"	NCQ
	DiamondMax 22	STM31000340AS	1TB	MX15	3.0Gbps	32MB	3.5"	NCQ
		STM3750330AS	750GB	MX15	3.0Gbps	16MB	3.5"	NCQ
SAMSUNG	Spinpoint F1R	HE103UJ	1TB	1AA01111	3.0Gbps	32MB	3.5"	NCQ
		HE753LJ	750GB	1AA01117	3.0Gbps	32MB	3.5"	NCQ
		HE502UJ	500GB	1AA01113	3.0Gbps	32MB	3.5"	NCQ
SEAGATE	Constellation ES	ST31000524NS	1TB	CC11	3.0Gbps	32MB	3.5"	NCQ
		ST32000644NS	2TB	SN11	3.0Gbps	64MB	3.5"	NCQ
	Barracuda ES.2	ST31000340NS	1TB	SN06	3.0Gbps	32MB	3.5"	NCQ
		ST3750330NS	750GB	SN06	3.0Gbps	32MB	3.5"	NCQ
		ST3500320NS	500GB	SN06	3.0Gbps	32MB	3.5"	NCQ
	Barracuda ES	ST3750640NS	750GB	3.AEK	3.0Gbps	16MB	3.5"	NCQ
		ST3500630NS	500GB	3.AEG	3.0Gbps	16MB	3.5"	NCQ
	Barracuda LP	ST31500541AS	1.5TB	CC34	3.0Gbps	32MB	3.5"	NCQ
	SV35.4	ST3320410SV	320GB	CV12	3.0Gbps	16MB	3.5"	NCQ
	SV35.3	ST31000340SV	1TB	SV16	3.0Gbps	32MB	3.5"	NCQ
		ST3750330SV	750GB	SV16	3.0Gbps	32MB	3.5"	NCQ
		ST3500320SV	500GB	SV17	3.0Gbps	32MB	3.5"	NCQ
	Pipeline HD .2	ST31000322CS	1TB	SC13	3.0Gbps	8MB	3.5"	NCQ
	Barracuda	ST1000DM003	1TB	CC4E	6.0Gbps	64MB	3.5"	NCQ
	Barracuda	ST2000DM001	2TB	CC4E	6.0Gbps	64MB	3.5"	NCQ
	Barracuda	ST3000DM001	3TB	CC43	6.0Gbps	64MB	3.5"	NCQ

TOSHIBA	TOSHIBA	DT01ACA100(HDS721010DLE630)	1TB	A650	6.0Gbps	32MB	3.5"	NCQ
	TOSHIBA	DT01ACA200(HDS723020BLE640)	2TB	AB0	6.0Gbps	64MB	3.5"	NCQ
	TOSHIBA	DT01ACA300(HDS723030BLE640)	3TB	AB0	6.0Gbps	64MB	3.5"	NCQ
	TOSHIBA	MK1002TSKB	1TB	MT2A	3.0Gbps	64MB	3.5"	NCQ
	TOSHIBA	MK2002TSKB	2TB	MT2A	3.0Gbps	64MB	3.5"	NCQ
WDC	WD RE4-GP	WD2002FYPS	2TB	04.05G04	3.0Gbps	64MB	3.5"	NCQ
	WD RE3	WD1002FBYS	1TB	03.00C05	3.0Gbps	32MB	3.5"	NCQ
		WD7502ABYS	750GB	03.00C05	3.0Gbps	32MB	3.5"	NCQ
		WD5002ABYS	500GB	02.03B02	3.0Gbps	16MB	3.5"	NCQ
		WD3202ABYS	320GB	02.03B02	3.0Gbps	16MB	3.5"	NCQ
	WD RE2-GP	WD1000FYPS	1TB	02.01B01	3.0Gbps	16MB	3.5"	NCQ
		WD7500AYPS	750GB	02.01B01	3.0Gbps	16MB	3.5"	NCQ
		WD5000ABPS	500GB	02.01B01	3.0Gbps	16MB	3.5"	NCQ
	WD RE2	WD7500AYYS	750GB	30.04G30	3.0Gbps	16MB	3.5"	NCQ
		WD5001ABYS	500GB	59.01D01	3.0Gbps	16MB	3.5"	NCQ
		WD3201ABYS	320GB	13.01C02	3.0Gbps	16MB	3.5"	NCQ
		WD1601ABYS	160GB	06.06H05	3.0Gbps	16MB	3.5"	NCQ
	WD AV-GP	WD20EURLS	2TB	51.0AB51	3.0Gbps	64MB	3.5"	NCQ
		WD20EVDLS	2TB	01.00A01	3.0Gbps	32MB	3.5"	NCQ
		WD15EVDLS	1.5TB	01.00A01	3.0Gbps	32MB	3.5"	NCQ
		WD10EVDLS	1TB	01.01A01	3.0Gbps	32MB	3.5"	NCQ
		WD10EVLVS	1TB	01.01A01	3.0Gbps	16MB	3.5"	NCQ
		WD7500AVVS	750GB	01.01A01	3.0Gbps	8MB	3.5"	NCQ
		WD5000AVVS	500GB	05.04C05	3.0Gbps	8MB	3.5"	NCQ
	WD Caviar Green	WD20EADS	2TB	01.00A01	3.0Gbps	32MB	3.5"	NCQ
		WD10EACS	1TB	01.01B01	3.0Gbps	16MB	3.5"	NCQ
		WD7500AACS	750GB	01.01B01	3.0Gbps	16MB	3.5"	NCQ
		WD6400AACS	640GB	05.04C05	3.0Gbps	16MB	3.5"	NCQ
		WD5000AACS	500GB	01.01B01	3.0Gbps	16MB	3.5"	NCQ
		WD30EZRS	3TB	80.00A80	3.0Gbps	64MB	3.5"	NCQ
		WD20EARS	2TB	80.00A80	3.0Gbps	64MB	3.5"	NCQ
		WD15EARS	1.5TB	80.00A80	3.0Gbps	64MB	3.5"	NCQ
	WD Caviar Black	WD2001FASS	2TB	05.01D05	3.0Gbps	64MB	3.5"	NCQ
		WD1001FALS	1TB	05.00K05	3.0Gbps	32MB	3.5"	NCQ
		WD7501AALS	750GB	05.00K05	3.0Gbps	32MB	3.5"	NCQ
		WD5001AALS	500GB	01.03B01	3.0Gbps	32MB	3.5"	NCQ
		WD6401AALS	640GB	01.03B01	3.0Gbps	32MB	3.5"	NCQ
	WD VelociRaptor	WD3000HLFS	300GB	04.04V01	3.0Gbps	16MB	3.5"	NCQ
		WD1500HLFS	150GB	04.04V01	3.0Gbps	16MB	3.5"	NCQ
	WD Caviar Blue	WD7500AAKS	750GB	30.04G30	3.0Gbps	16MB	3.5"	
		WD6400AAKS	640GB	01.03B01	3.0Gbps	16MB	3.5"	NCQ
		WD5000AAKS	500GB	30.04G30	3.0Gbps	16MB	3.5"	NCQ
		WD4000AAKS	400GB	12.01C01	3.0Gbps	16MB	3.5"	NCQ

 We always recommend the use of Enterprise Class SATA Hard Drives as Enterprise Class SATA Drives support TLER (Time Limited Error Recovery), Higher MTBF, Higher Duty Cycles and typically include a sensor for rotation and vibration.

2. USB Host

i. MB chipset built in USB

South Bridge / MB	Operating System
South Bridge: Intel FW 82801IR(ICH9R) MB: MSI MS-7338 P35 Platinum Combo	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
South Bridge: Intel FW 82801IR(ICH9R) MB: ASUS P5E3 Premium	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
South Bridge: NVIDIA nForce 750i SLI MB: ASUS P5N-D	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
South Bridge: AMD SB600 MB: MSI K9A2 Platinum	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2

South Bridge: NVIDIA nForce 430i (MCP51) MB: MSI P7N SLI Platinum	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
South Bridge: Intel ICH10 MB: GIGABYTE GA-EP45-DS3L	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
South Bridge: AMD SB600 MB: ECS AMD690GM-M2	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
South Bridge: Intel ICH7 MB: FOXCONN 45CMX-K	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
South Bridge: NVIDIA nForce 430 SLI MCP MB: ABIT FP-IN9 SLI	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2

South Bridge: AMD SB600 MB: GIGABYTE GA-MA790FX-DQ6	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
South Bridge: Intel [®] ICH10R MB: GIGABYTE GA-EG45M-DS2H	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
South Bridge: Intel [®] P55 MB: GIGABYTE P55-UD3P	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
Min MAC	MAC 10.5.7
MACBook Pro	MAC 10.5.7
MAC Pro	MAC 10.4.11
MAC Power G4	MAC 10.4.11
iMAC	MAC 10.6.2

ii. USB Host Adaptors

USB ASIC / USB HBA	Operating System
USB ASIC: VIA VT6212L USB HBA: ATEN UF-220	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
USB ASIC: VIA VT6212L USB HBA: Billionton P1394U2V-B	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate

3. IEEE 1394 Host

i. MB built in IEEE 1394a

IEEE 1394 ASIC / MB	Operating System
IEEE 1394 ASIC: VIA VT 6308P MB: MSI MS-7338 P35 Platinum Combo	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
IEEE 1394 ASIC: Agere® L-FW3227 1394a MB: ASUS P5E3 Premium	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
IEEE 1394 ASIC: VIA VT6308P MB: ASUS P5N-D	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
IEEE 1394 ASIC: VIA VT 6308P MB: MSI P7N SLI Platinum	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
IEEE 1394 ASIC: VIA VT6308P MB: MSI K9A2 Platinum	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2

IEEE 1394 ASIC: TI TSB43AB23 MB: GIGABYTE GA-MA790FX-DQ6	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
IEEE 1394 ASIC: TI TSB43AB23 MB: GIGABYTE GA-EG45M-DS2H	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
MAC Mini	MAC 10.5.7
MAC Pro	MAC 10.4.11
MAC Power G4	MAC 10.4.11

ii. MB built in IEEE 1394b

IEEE 1394 ASIC / MB	Operating System
MAC Mini	MAC 10.5.7
MACBook Pro	MAC 10.5.7
MAC Pro	MAC 10.4.11
MAC Power G4	MAC 10.4.11
iMAC	MAC 10.6.2

iii. IEEE 1394a Host Adaptors

IEEE 1394 ASIC / IEEE 1394 HBA	Operating System
IEEE 1394 ASIC: VIA VT6306 IEEE 1394 HBA: ATEN UF-220	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
IEEE 1394 ASIC: VIA VT6306 IEEE 1394 HBA: Billionton P1394U2V-B	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
IEEE 1394 ASIC: LSI L-FW323-06 IEEE 1394 HBA: INTOPIC HU-1394Ai	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
IEEE 1394 ASIC: 86ALT6W-TSB82AA2 IEEE 1394 HBA: Uptech UT1394 Combo	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
IEEE 1394 ASIC: VIA VT6303 IEEE 1394 HBA: Dynamalink D1394PB	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2

	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
IEEE 1394 ASIC: TI TSB43AB23 IEEE 1394 HBA: Uptech UT1394	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
IEEE 1394 ASIC: TI XIO2213AZAY IEEE 1394 HBA: Uptech UT1394 (A+B)	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
IEEE 1394 ASIC: TSB41LV03A+ TSB43AB22A IEEE 1394 HBA: Galileo IEEE 1394	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2

iv. IEEE 1394b Host Adaptors

IEEE 1394 ASIC / IEEE 1394 HBA	Operating System
IEEE 1394 ASIC: TI XIO2213AZAY IEEE 1394 HBA: Uptech UT1394 (A+B)	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate

4. eSATA Host

i. MB built in eSATA port

eSATA port / MB	Operating System
South Bridge: Intel FW 82801IR(ICH9R) MB: MSI MS-7338 P35 Platinum Combo	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
eSATA ASIC: Jmicron JMB383 MB: ASUS P5E3 Premium	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
eSATA ASIC: Jmicron JMB383 MB: MSI P7N SLI Platinum	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
South Bridge: Intel ICH10R MB: GIGABYTE GA-EG45M-DS2H	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate

ii. MB built in SATA port (connected via eSATA bracket)

SATA port / MB	Operating System
South Bridge: Intel FW 82801IR(ICH9R) MB: MSI MS-7338 P35 Platinum Combo	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
South Bridge: Intel FW 82801IR(ICH9R) MB: ASUS P5E3 Premium	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
South Bridge: NVIDIA nForce 750i SLI MB: ASUS P5N-D	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
South Bridge: AMD SB600 MB: MSI K9A2 Platinum	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
South Bridge: NVIDIA nForce 430i (MCP51) MB: MSI P7N SLI Platinum	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2

	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
South Bridge: Intel ICH10 MB: GIGABYTE GA-EP45-DS3L	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
South Bridge: AMD SB600 MB: ECS AMD690GM-M2	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
South Bridge: Intel ICH7 MB: FOXCONN 45CMX-K	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
South Bridge: NVIDIA nForce 430 SLI MCP MB: ABIT FP-IN9 SLI	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
South Bridge: AMD SB600 MB: GIGABYTE GA-MA790FX-DQ6	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
South Bridge: Intel [®] ICH10R MB: GIGABYTE GA-EG45M-DS2H	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate

South Bridge: Intel® P55	Windows 7 32BIT Ultimate
MB: GIGABYTE P55-UD3P	Windows 7 64BIT Ultimate

iii. eSATA Host Adaptors

eSATA ASIC / eSATA Host	Operating System
eSATA Host: Promise NS4600	Embedded Linux
eSATA ASIC: Promise PDC40718	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
eSATA HBA: Promise FastTrak TX4302	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
eSATA ASIC: Promise PDC20775	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
eSATA HBA: Promise FastTrak TX4650	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
eSATA ASIC: Jmicron JMB363	Windows XP 32bit Professional With SP3
	Windows XP 64bit XP 64 With SP2
eSATA HBA: Galileo PEES111A	Windows Vista 32bit Enterprise With SP2
	Windows Vista 64bit Enterprise With SP2
	Windows Server 2003 R2 32bit Enterprise With SP2
	Windows Server 2003 R2 64bit Enterprise With SP2
	Windows Server2008 32bit enterprise With SP2
	Windows Server2008 64bit enterprise With SP2
	Windows 7 32BIT Ultimate
	Windows 7 64BIT Ultimate
eSATA ASIC: Silicon Image Sli3132CNU	MAC OS 10.6.8
	Read:120 Mbps
eSATA HBA: SeriTek 2SE2-E	Writw:119.68 Mbps
eSATA ASIC: Marvell 88SX7042	MAC OS 10.6.8
	Read:160 Mbps
eSATA HBA: SeriTek ME4-4	Writw:211 Mbps
eSATA ASIC: Asmedia ASM1061	MAC OS 10.6.8
	Read:250 Mbps
eSATA HBA: BIOSTAR DCS34A	Writw:220 Mbps

Technical Notes:

1. **Single Volume support** – DS4600 only supports a single volume whether using RAID 0, RAID 1, RAID 5 or RAID 10.
2. **Windows XP 32bit and Windows 2003 32bit** have 2TB Limitation for volumes. This is an OS limitation. To support volumes over 2TB please use Windows XP 64bit, Windows 2003 64bit, Windows Vista, Windows 2008 or Windows 7.
3. **SmartNAVI will fail to create volume larger than 2TB** – SmartNAVI cannot create volume larger than 2TB under Windows XP 32bit and Windows 2003 32bit. Windows XP 64bit, Windows Vista, Windows 2008 and Windows 7 are not affected.
4. **eSATA and Motherboard BIOS** depends on Enhanced or Advanced support from System BIOS and or OS Drivers. For instance, some AMD 700 series chipsets required the SATA Mode to be set at “Enhanced or AHCI” for DS4600 to be properly detected and also work with SmartNAVI.
5. **eSATA and SmartNAVI** – some chipsets and HBA do not support pass through commands. The end result is DS4600 is not detected by SmartNAVI but has no problem with detection by Chipset, System BIOS or HBA.

Known ASIC

1. JMicron series
2. Promise series
3. Nvidia series
4. Marvell series

Please use USB or Firewire host interface to configure via SmartNAVI, and then move back to eSATA afterwards.

6. **USB Cable Length** – Cables longer than 1.8M are not supported or approved for use with the DS4600. Use longer cables at your own risk.
7. **eSATA Hot-Plug under Windows fails** – Windows Native SATA Driver does not support Hot-Plug therefore you will need to attached eSATA cable to PC before computer “power-on” or force Windows to scan for New Hardware. To scan for new hardware, right click on My Computer, select Manage, select Device Manager from pane on the left, then right click on your “computers hostname” (top center) and select “Scan for Hardware Changes”. Windows should detect the DS4600 and install appropriate drivers. If this fails to work, reboot and make sure DS4600 is detected by System BIOS or HBA BIOS.

8. Connection issues with any Firewire HBA using Texas Instruments **TI TSB43AB22 or TSB43AB23 ASIC under Windows 2003 32bit and 64bit** – Microsoft has a hotfix to address the issue here:

For TI TSB43AB22, please install

<http://support.microsoft.com/kb/958347>

For TI TSB43AB23, please install

<http://support.microsoft.com/kb/958149>

9. **VIA VIA6308P Firewire ASIC** – Suffers from poor performance under Windows 2003 32bit and 64bit. Issue is with Native Firewire driver provided by the OS. Use either different FW HBA, use 3rd Firewire Driver or move to Windows 2008, Windows Vista or Windows 7.
10. **Nvidia South Bridge Driver prevents successful RAID creation and or format of DS4600** – RAID Creation will fail and volume type will be RAW. In some cases the Creation is successful but wrong capacity is reported. Please use Windows Native driver and not driver supplied by Nvidia.