NORTHFIELD MUTUAL INSURANCE CO.

Personal Auto Claims | PO Box 30455, Columbus, OH 43230
claims@northfieldmutual.example | 800-555-0190

AUTOMOBILE LOSS NOTICE

First Notice of Loss (FNOL) - Form NM-AL-01 (rev. 03/26)

REPORTING

FNOL REFERENCE	DATE REPORTED	REPORTED VIA	REPORTED BY
FNOL-20261076	09/27/2026	Web portal	Named insured

POLICY & INSURED

POLICY NUMBER	NAMED INSURED	PHONE
NFM-PA-4473118	Thomas Reyes	614-555-0109

MAILING ADDRESS	LINE OF BUSINESS
304 Linden Ave, Bexley, OH 43209	Personal auto

LOSS INFORMATION

DATE OF LOSS	TIME	LOCATION OF LOSS
09/26/2026	11:30	Drexel Ave near Main St, Bexley, OH

TYPE OF LOSS	COVERAGE CLAIMED
Single-vehicle - fixed object	Collision

DESCRIPTION OF ACCIDENT / LOSS

Insured misjudged a turn and struck a stone planter with the front of the vehicle. Bumper, hood and fender damaged.

INSURED VEHICLE

YEAR	MAKE	MODEL	VIN
2024	Tesla	Model 3 RWD	5YJW20555RB331509

PLATE	DRIVABLE?	WHERE CAN VEHICLE BE SEEN
TSL-3001	Yes	Olentangy Auto Body

OTHER PARTY

OTHER DRIVER NAME	PHONE	OTHER VEHICLE
N/A		

OTHER PARTY INSURER	OTHER PARTY POLICY NO.

INJURIES

Any injuries? ☐ Yes ☒ No

INJURY DETAILS (NAME, NATURE OF INJURY, TREATMENT)

POLICE / AUTHORITIES

AGENCY	REPORT NUMBER	OFFICER / BADGE
None reported		

Any person who knowingly presents a false or fraudulent claim for payment of a loss may be subject to criminal and civil penalties. SYNTHETIC TEST DATA - NOT A REAL CLAIM.

Olentangy Auto Body

915 W Dublin-Granville Rd, Worthington, OH 43085 | 614-555-0311

PRELIMINARY ESTIMATE

Estimate #: E-560692 Date: 09/27/2026

Customer: Thomas Reyes
Phone: 614-555-0109
Insurance: Northfield Mutual Insurance Co.
Claim/Policy: NFM-PA-4473118

Vehicle: 2024 Tesla Model 3 RWD
VIN: 5YJW20555RB331509
Plate: TSL-3001
Loss date: 09/26/2026

#	Operation / description	Part $	Labor hrs	Labor $	Line total
1	Repl Front bumper cover	$384.14	2.5	$155.00	$539.14
2	Repl Grille assembly	$455.54	0.6	$37.20	$492.74
3	Repl Headlamp assy R	$517.49	0.5	$31.00	$548.49
4	Repl Bumper reinforcement	$389.42	1.1	$68.20	$457.62
5	Repl Hood panel	$642.10	1.9	$117.80	$759.90
6	Repl Fender R	$187.13	1.6	$99.20	$286.33
7	Rpr Radiator support (repair)		3.6	$223.20	$223.20
8	Repl AC condenser	$533.80	1.2	$74.40	$608.20
9	Repl Radiator	$239.90	1.5	$93.00	$332.90
10	Repl Headlamp assy L	$498.63	0.5	$31.00	$529.63
11	Repl Fender L	$539.48	1.6	$99.20	$638.68
12	Repl Cooling fan assy	$619.22	0.9	$55.80	$675.02
13	Subl Sublet: frame measure, 4-wheel alignment, pre/post scan			$720.77	$720.77
14	Refinish Paint materials (5.9 refinish hrs @ $38.00)				$224.20

Parts	$5,006.85
Labor (body @ $62.00/hr, incl. sublet)	$1,805.77
Paint materials	$224.20
Sales tax 8.0% (parts & materials)	$418.48
GRAND TOTAL	**$7,455.30**

This is a preliminary estimate based on visible damage. Hidden damage may be found once teardown begins and will be submitted as a supplement. Deductible, if any, is the responsibility of the vehicle owner. SYNTHETIC TEST DATA.