NORTHFIELD MUTUAL INSURANCE CO.

Personal Auto Claims | PO Box 30455, Columbus, OH 43230
claims@northfieldmutual.example | 800-555-0190

AUTOMOBILE LOSS NOTICE

First Notice of Loss (FNOL) - Form NM-AL-01 (rev. 03/26)

REPORTING

FNOL REFERENCE	DATE REPORTED	REPORTED VIA	REPORTED BY
FNOL-20261043	09/07/2026	Web portal	Named insured

POLICY & INSURED

POLICY NUMBER	NAMED INSURED	PHONE
NFM-PA-4472844	Kevin Thornbury	614-555-0113

MAILING ADDRESS	LINE OF BUSINESS
120 Station St Apt 4B, Columbus, OH 43215	Personal auto

LOSS INFORMATION

DATE OF LOSS	TIME	LOCATION OF LOSS
09/06/2026	02:15	Front St near Spring St, Columbus, OH

TYPE OF LOSS	COVERAGE CLAIMED
Single-vehicle - fixed object	Collision

DESCRIPTION OF ACCIDENT / LOSS

Lost control on wet pavement and hit a utility pole. Front end heavily damaged. Vehicle towed.

INSURED VEHICLE

YEAR	MAKE	MODEL	VIN
2022	Volkswagen	Jetta SE	3VW8BH0W3ND039117

PLATE	DRIVABLE?	WHERE CAN VEHICLE BE SEEN
MCR-0937	No - towed	Buckeye Collision Center

OTHER PARTY

OTHER DRIVER NAME	PHONE	OTHER VEHICLE
N/A		

OTHER PARTY INSURER	OTHER PARTY POLICY NO.

INJURIES

Any injuries? ☐ Yes ☒ No

INJURY DETAILS (NAME, NATURE OF INJURY, TREATMENT)

POLICE / AUTHORITIES

AGENCY	REPORT NUMBER	OFFICER / BADGE
Columbus Division of Police	CPD-26-1187402	Ofc. J. Patel #2291

Any person who knowingly presents a false or fraudulent claim for payment of a loss may be subject to criminal and civil penalties. SYNTHETIC TEST DATA - NOT A REAL CLAIM.

Buckeye Collision Center

2280 Morse Rd, Columbus, OH 43229 | 614-555-0300

PRELIMINARY ESTIMATE

Estimate #: E-560581 Date: 09/07/2026

Customer: Kevin Thornbury
Phone: 614-555-0113
Insurance: Northfield Mutual Insurance Co.
Claim/Policy: NFM-PA-4472844

Vehicle: 2022 Volkswagen Jetta SE
VIN: 3VW8BH0W3ND039117
Plate: MCR-0937
Loss date: 09/06/2026

#	Operation / description	Part $	Labor hrs	Labor $	Line total
1	Repl Front bumper cover	$759.42	3.4	$210.80	$970.22
2	Repl Hood panel	$193.12	2.6	$161.20	$354.32
3	Repl Radiator	$644.63	2.1	$130.20	$774.83
4	Repl AC condenser	$301.85	1.7	$105.40	$407.25
5	Repl Fender R	$276.77	2.3	$142.60	$419.37
6	Repl Headlamp assy R	$229.69	0.7	$43.40	$273.09
7	Rpr Frame rail R (repair)		8.6	$533.20	$533.20
8	Repl Bumper reinforcement	$882.12	1.6	$99.20	$981.32
9	Repl Radiator support	$581.30	6.4	$396.80	$978.10
10	Repl Cooling fan assy	$695.99	1.3	$80.60	$776.59
11	Repl Grille assembly	$328.48	0.9	$55.80	$384.28
12	Repl Headlamp assy L	$880.71	0.7	$43.40	$924.11
13	Repl Front wheel R	$465.24	0.6	$37.20	$502.44
14	Repl Lower control arm R	$798.40	1.9	$117.80	$916.20
15	Repl Tie rod end R	$249.28	1.1	$68.20	$317.48
16	Subl Sublet: frame measure, 4-wheel alignment, pre/post scan			$931.71	$931.71
17	Refinish Paint materials (5.2 refinish hrs @ $38.00)				$197.60

Parts	$7,287.00
Labor (body @ $62.00/hr, incl. sublet)	$3,157.51
Paint materials	$197.60
Sales tax 8.0% (parts & materials)	$598.77
GRAND TOTAL	**$11,240.88**

This is a preliminary estimate based on visible damage. Hidden damage may be found once teardown begins and will be submitted as a supplement. Deductible, if any, is the responsibility of the vehicle owner. SYNTHETIC TEST DATA.

COLUMBUS DIVISION OF POLICE

Incident Report - Abstract (Insurance Copy)

Report no.	CPD-26-1187402
Incident type	Motor vehicle crash
Date/time of incident	09/06/2026 approx. 02:15
Location	Front St near Spring St, Columbus, OH
Date reported to agency	09/06/2026
Reporting officer	Ofc. J. Patel #2291

Units / persons involved

Unit 1: 2022 Volkswagen Jetta SE, plate MCR-0937 (OH). Driver/owner: Kevin Thornbury.

Narrative

Officers responded to a single-vehicle crash. Unit 1 left the roadway and struck utility pole #COL-55871. Driver stated the road was wet and he lost traction. Light rain at time of crash. Driver declined medical. AEP notified of pole damage. Vehicle towed by Rapid Recovery Towing.

This abstract is provided for insurance purposes only. SYNTHETIC TEST DATA.