



Power at the measured fine-control endpoints



Connected branches omit the output retimer, GHz clock receiver, full control and real bias generators. This is not total PLL power.