

API No. <u>42-001-32872</u> Drilling Permit # <u>916248</u> SWR Exception _____		RAILROAD COMMISSION OF TEXAS OIL & GAS DIVISION APPLICATION FOR PERMIT TO DRILL, RECOMPLETE, OR RE-ENTER <i>This facsimile W-1 was generated electronically from data submitted to the RRC.</i> <i>A certification of the automated data is available in the RRC's Austin office.</i>				FORM W-1 07/2004 Permit Status: Approved	
1. RRC Operator No. 872178		2. Operator's Name (as shown on form P-5, Organization Report) TSAR ENERGY, LLC		3. Operator Address (include street, city, state, zip): 5600 W. LOVERS LANE STE 116-545 DALLAS, TX 75209-0000			
4. Lease Name THOMPSON		5. Well No. 3					
GENERAL INFORMATION							
6. Purpose of filing (mark ALL appropriate boxes): ☒ New Drill ☐ Recompletion ☐ Reclass ☐ Field Transfer ☐ Re-Enter ☐ Amended ☐ Amended as Drilled (BHL) (Also File Form W-1D)							
7. Wellbore Profile (mark ALL appropriate boxes): ☒ Vertical ☐ Horizontal (Also File Form W-1H) ☐ Directional (Also File Form W-1D) ☐ Sidetrack							
8. Total Depth 710		9. Do you have the right to develop the minerals under any right-of-way ? ☒ Yes ☐ No		10. Is this well subject to Statewide Rule 36 (hydrogen sulfide area)? ☐ Yes ☒ No			
SURFACE LOCATION AND ACREAGE INFORMATION							
11. RRC District No. 06		12. County ANDERSON		13. Surface Location ☒ Land ☐ Bay/Estuary ☐ Inland Waterway ☐ Offshore			
14. This well is to be located <u>2.5</u> miles in a <u>NW</u> direction from <u>Slocum</u> which is the nearest town in the county of the well site.							
15. Section	16. Block	17. Survey ERWIN, R		18. Abstract No. A-263	19. Distance to nearest lease line: ft.	20. Number of contiguous acres in lease, pooled unit, or unitized tract: 65	
21. Lease Perpendiculars: <u>672</u> ft from the <u>SOUTH</u> line and <u>618</u> ft from the <u>EAST</u> line. 22. Survey Perpendiculars: <u>3460</u> ft from the <u>SOUTH</u> line and <u>618</u> ft from the <u>EAST</u> line.							
23. Is this a pooled unit? ☐ Yes ☒ No		24. Unitization Docket No:		25. Are you applying for Substandard Acreage Field? ☐ Yes (attach Form W-1A) ☒ No			
FIELD INFORMATION List all fields of anticipated completion including Wildcat. List one zone per line.							
26. RRC District No.	27. Field No.	28. Field Name (exactly as shown in RRC records)		29. Well Type	30. Completion Depth	31. Distance to Nearest Well in this Reservoir	
06	84144001	SLOCUM		Oil Well	695	250.00	
BOTTOMHOLE LOCATION INFORMATION is required for DIRECTIONAL, HORIZONTAL, AND AMENDED AS DRILLED PERMIT APPLICATIONS							
Remarks See W1 Comments attached				Certificate: I certify that information stated in this application is true and complete, to the best of my knowledge. <u>Samuel Cheatham, TSAR Energy, LLC</u> <u>Jun 04, 2026</u> Name of filer Date submitted <u>(469)571-9090</u> <u>scheatham@tsarenergy.com</u> Phone E-mail Address (OPTIONAL)			
RRC Use Only				Data Validation Time Stamp: Aug 4, 2026 12:17 PM('As Approved' Version)			

Permit Status:	Approved
<i>The RRC has not approved this application. Duplication or distribution of information is at the user's own risk.</i>	

**RAILROAD COMMISSION OF TEXAS
OIL & GAS DIVISION**

APPLICATION FOR PERMIT TO DRILL, RECOMPLETE, OR RE-ENTER

*This facsimile W-1 was generated electronically from data submitted to the RRC.
A certification of the automated data is available in the RRC's Austin office.*

W-1 Comments

Permit #	916248
Approved Date:	Aug 04, 2026

[RRC STAFF Jun 9, 2026 2:25 PM]: There have been problems identified with this permit (see problem letter attachment). Notification sent.; [RRC STAFF Jun 11, 2026 9:47 AM]: A revised plat has been submitted.; [RRC STAFF Jun 11, 2026 9:48 AM]: According to the filer, this is not a pooled unit. The acreage shown on the plat is mineral lease tracts.; [RRC STAFF Jun 11, 2026 9:48 AM]: Problems identified with this permit are resolved.; [RRC STAFF Jun 11, 2026 9:58 AM]: A revised plat has been submitted adding lease line boundaries and distance to the nearest well.; [RRC STAFF Jun 11, 2026 10:01 AM]: There have been problems identified with this permit (see problem letter attachment). Notification sent.; [RRC STAFF Aug 4, 2026 12:17 PM]: Problems identified with this permit are resolved.