

Report

Site Security Weekly Report

Reference No :

Version No

Week No : 29

Prepared by:

Position / Title	Name	Signature	Date
IT Manager	Rynel Yanes		07-22-2019
Site Technical Security Administrator	Jeremiah Nantona		07-22-2019

The information contained in this document is a property of OAMPI Inc. It may not be copied, reproduced, released to any third party, or used in any other way without the expressed prior written consent of the owner of this document.



NVR Memory Status

172.17.0.80		
HDD No.	Capacity	Free Space
1	3726.02GB	0.00GB
2	3726.02GB	0.00GB
172.17.0.81		
HDD No.	Capacity	Free Space
1	3726.02GB	0.00GB
2	3726.02GB	0.00GB
172.22.1.50		
HDD No.	Capacity	Free Space
1	3726.02GB	0.00GB
2	3726.02GB	0.00GB



PROXIMITY CARD MONITORING

JAKA	Quantity
Number of blank proximity card	0
Number of proximity card/Company issued fromjuly1	0
G2	Quantity
Number of available HID	5
Number of HID/Temporary ID issued from July1	00
Number of missing HID	2
Number of blank proximity card	0
Number of proximity card/Company issued from July1	00



FIRMWARE UPDATE FOR CCTV Cameras and NVRs

CCTV CAMERA - NO Available update based on their web Pages:

https://us.hikvision.com/en/support-resources/cybersecurity-

center/updating-firmware

https://www.hikvision.com/en/Support/Downloads/Firmware/DVR/Turbo-1.0-DVR

NVR: Firmware is up to date based on their web page.

https://www.hikvision.com/en/Support/Downloads/Firmware/NVR#prettyPhoto



WEEKLY UPS MONITORING:





Projected Site Security Requirements

- Pin-cables for SCR-100 for testing of anti pass-back- still looking on hardware near Glorietta 2
- 2. Colored Ribbon- Miss Honey already send the Quotation to IT manager
- Theia is already on the vendor for repair(Warranty covered)
 Door access of ph1 IT HUB Room, 8th floor and 5th floor in.



Analysis and Recommendations

1. Analysis:

5th floor ext Door Access:

- -Cancelled (Not critical).
- -Pin Cables for SCR-100 testing of Anti Pass-back
- -Pin Cables is not available at RAON
- -Door Access for advent
- -Theia (172.22.1.50) hardware issue.
- Door access of ph1 IT HUB Room, 8^{th} floor and 5^{th} floor in (Hardware or software issue)



Recommendations:

5th floor extension

-Cancelled / not critical

Door access with anti-pass back

-Contact several vendors on zkt scr100 and how anti passback works.

-Door Access for advent

Delivery of SI today (July 22, 2019)

Theia (172.22.1.50) hardware issue.

-Still on isolation of the vendor

Door access of ph1 IT HUB Room, 8^{th} floor and 5^{th} floor in (Hardware or software issue)

- 5th floor and 8th floor device is already fix.
- Made a test environment at G2 to test the ph1 IT Hub Room door access