

NATIONAL PROPERTY INSPECTORS

PROPERTY INSPECTION REPORT

Property Address:	1248 Commercial Blvd, Suite 100	Report Date:	July 25, 2026
Client:	Horizon Commercial Realty	Inspector:	James Albright (Lic #4920)

Summary of Findings

SYSTEM CATEGORY	CONDITION	INSPECTOR OBSERVATIONS & RECOMMENDATIONS
Structural & Foundation	Satisfactory	No major settlement cracks or structural defects noted along visible slab edges.
Roofing & Gutters	Marginal	Minor membrane weathering near south parapet wall. Recommend elastomeric sealing within 6 months.
Electrical Systems	Satisfactory	200A main panel properly grounded and labeled. Circuit breaker load test passed.
Plumbing & Drainage	Action Required	Slow drainage noted in breakroom double sink. Cleanout access showed grease buildup. Requires hydro-jetting.
HVAC / Environmental	Satisfactory	Dual rooftop heat pump units operational and maintaining 72 deg F indoor temperature.

Overall Summary Comments

Overall commercial unit is in good functional condition. Primary item requiring immediate attention prior to lease execution is the plumbing cleanout in the employee breakroom.

CERTIFIED INSPECTOR SIGNATURE

CLIENT ACKNOWLEDGMENT SIGNATURE