

- 1. CHARGING ON: CH "1"
- 2. WAIT UNTIL THE CHARGE IS ACCUMULATED
- 3. CHARGING OFF: CH "0"
- 4. RELEASE CHARGE INTO THE FLIP-DISC: PL"1"
- 5. WAIT 1ms
- 6. TURN OFF THE CURRENT PULSE: PL"0" WWW.FLIPO.IO



FLIP-DISC F	PIII SE SHAPER	POWER SUPPLY
	OLSE SHAPER	POWER SUPPLI

VIN: 12V; 1.5A

PL, CH - 3.3V-5V VOLTAGE LEVEL

PSPS-12V V1

DATE: 12.01.2023