WESTBROOK MATERIAL TEST REPORT

1111 Lockwood Dr.
Houston, Tx 77020

Voice 713 675 6438
Fax 713 675 9742

To: *005625 MAVERICK INTERNATIONAL LTD* **Printed:** *6/19/2026*

Description:
2 X 6 S80 A106B BLK SMLS NPL PXT

******** Specifications - Heat Code W24529: ********
A106-19 GR.B, SA106 GR.B, A234-19 WPB, SA234 WPB, A530, A733, ASME B36.10, B1.20.1, MSS SP-25, SP-95
STARTING MATERIAL: A106B PIPE & TUBE

Chemical Composition %:

C:	Mn:	P:	S:	Si:	Cr:	Ni:	Mo:
0.173	*0.790*	*0.009*	*0.007*	*0.180*	*0.050*	*0.070*	*0.020*
Cu:	**V:**	**Cb/Nb:**	**Ti:**	**B:**	**C.E.:**		
0.150	*0.021*	*0.001*	*0.001*	*.0003*	*.337*		

Mechanical Properties:

Tensile(PSI):	Yield(PSI):	Elong(%):	Hardness:	Bend:	Hydro(PSI):
75380	*51320*	*35.00*	*HRB 79-80*	*PASSED*	*2970*

Comments:

Normalized 895C and 8 min, and still air cooled.
Product is compliant with NACE MR0175/ISO 15156 / Product is compliant with NACE MR0103.
No weld repair is performed.
The product is free of Mercury contamination.
Tensile test is taken from round specimen.
Yield Strength is determined using 0.2% offset method, unless otherwise specified.
When reported on the MTR: Tensile testing per ASTM E 8, Charpy impact testing per ASTM E 23 and Brinell Hardness Testing per ASTM E 10.
Products are manufactured in compliance to EN 10204 Type 3.1.

Producing pipe mill: Tubos Reunidos/Spain
Country of melt: Spain
Hot finished. Normalized.

This is a generically produced MTR. We certify only the chemistry and physical results shown for the referenced Heat Code as furnished by the Producing Mill. The description shown is the sole responsibility of the requesting party. This document was electronically produced and transmitted, and the product described is not warrantied by this document. This document does not warranty any items modified or altered from the original sales description.

Prop 65 Warning for California Residents - Products listed may contain chemicals including Nickle and/or Carbon known to the State of California to cause cancer, birth defects and other reproductive harm. http://www.p65warnings.ca.gov/