
Core to core latency on socket 0 with 3800MHz core and 800MHz uncore frequency





- 90