
Core to core latency on socket 0 with 800MHz core and 2500MHz uncore frequency





- 90