GLORY (PHILIPPINES), INC - Plant 5 Quality Assurance Department

Area: Packaging area (office)

Corrective Action:

1. Lower the secondary light or add additional LED light



2024 WEM Corrective Action (For Job Order)

Area: Parts Receiving (G181)

Corrective Action:

1. Provision of secondary light



Area: Parts Inspection office

Corrective Action:

1. Additional/Replacement of LED light



Area: Parts Inspection (inspection line 2)

Corrective Action:

1. Installation of secondary light



Area: Parts Inspection (Pull-out/POF)

Corrective Action:

1. Replacement of LED light

