


Installation Diagram - Pole Mounting



Installation Notes:

- Mount sensor facing downward
- Ensure unobstructed view of water
- Minimum height: 0.5m above max flood
- Secure cable with cable ties
- Use stainless steel brackets
- Apply waterproof sealant at joints