. Students/Trainees: These are personnel who are assigned to schools for training of less than 21 weeks.

. Recruits: These are personnel who have not received their initial MOS and are assigned to the MCRD's or other related installations for recruit training. They are housed in recruit open bay barracks.

. Transient (on TAD Orders): These are personnel both military and civilians who are on TAD Orders and contribute to the transient billeting fund. They are official Government travelers for purposes of site visits, conferences, meetings, etc.

. Meets or Exceeds Current Assignment Standards. Rooms that are currently considered acceptable for involuntary assignment for any one personnel category according to the Minimum Standards of Adequacy for assignment to existing inventory.

. Less than Assignment Stardards. Rooms that do not meet the Minimum Standards of Adequacy for assignment to existing inventory. Personnel assigned to these rooms are billeted at less than the assignment standard for their rank/grade; i.e., E-1-E-3 at 3 per room with a total of 180 net square feet.

. Inadequate Barracks by Facility Condition. Facilities that do not meet the minimum structural, environmental, and/or criteria of acceptability for involuntary assignment; and cannot be upgraded economically to meet minimum adequacy standards. This does not relate to assignment standards. This is a facility (structural) condition vice assignment.

. Adequate. Facilities that meet the minimum space, privacy and environmental standards of acceptability, and are acceptable for involuntary assignment for any one personnel category,

. Substandard. Facilities that do not meet the minimum acceptability standards for involuntary assignment, but may be made acceptable economically through improvement.

. Inadequate. See definition for Inadequate Barracks by Facility Condition above.