Time	11 us 12 us	13 us	14 us 1	5 tis 16 tis	17 ús	18 us
rst=x						
clk_ice=0				<u> </u>		
clk_ULPI=0						
clk_div_ice=0				 		
clk_div_ULPI=0				₼ ₼ ਜ਼ ਜ਼ ਜ਼ ਜ਼ ਜ਼ ਜ਼	<u> </u>	70000
clk_debounce=0						,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
IO_LEDs[4:0]=0				XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX		XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
UART						
clk_Rx=0						
Rx=1						
O_DATA[7:0]=xx	00					<u> </u>
clk_Tx=0			ANNONAN ANNONANANAN ANNONAN			
Tx=1						
I_DATA[7:0]=00	FF	X XXX03	<u> </u>			
		/AYYY\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\				
NxT=0						
send_data=0						
Rx_EMPTY=1						
Tx_FULL=0						
ULPI						
ADDR[5:0]=00	00					
PrR=0	34					
REG_VAL_R[7:0]=00 PrW=0	34					
REG_VAL_W[7:0]=00	E9					
1420_V112_W[/:0] 00	1					
ULPI_state_r[2:0]=000	001	X+ X001			X 001	
RxCMD[7:0]=00	96	X X 9 6			X B7	
USB_DATA[7:0]=xx	xx	(A4)(X) xx				
USB_INFO_DATA[15:0]=xxxx	xxxx	XXXX				
ULPI_DIR=0						
ULPI_DATA[7:0]=00	00)			X 00	
ULPI_NXT=0						
ULPI_RST=x ULPI_STP=0						
OLFI_SIF-0						
Operation buffer						
op_stack_pull=0						П
op_stack_msg[15:0]=xxxx	xxxx)(X+
op_stack_empty=1						
Main controller						
force_send=0	-	/AYA)~(>-				\ w /
MAIN_state_r[3:0]=0	0	XXX Xº				X 0
MAIN_cmd_r[1:0]=00	00					
ULPI_ADDR_r[5:0]=00 UART_Tx_DATA_r[7:0]=00	FF	X XXX03				
	-	WWA				
Buttons						
IO_BTNs[1:0]=11	11					
IO_BTNs[1]=1						
IO_BTNs[0]=1						
test_counter[31:0]=0	7	χ8			X 9 X 10	
Random						
toggle_r=0						
btn2_pulse=0						