## ee9 V6 ERRATA

• The timing of some magnetic tape operations is underestimated.

SIGNIFICANCE: NONE: HAS NO EFFECT ON CORRECT EXECUTION OF PROBLEM PROGRAMS.

V6.1A CORRECTS ALL OF THESE ERRORS IN V6.0A.