

MAINTENANCE REPORT

REPORT DATE	13/08/2026	BRANCH	Makkah	REPORT ID	MAK-REP-A013
TOTAL ENTRIES	7	TOTAL PROGRAMMING	0	TOTAL MAINTENANCE	11
TOTAL INSTALL	0	TOTAL DISMANTLE	1		

#	TEL#	ISSI#	MODEL	ISSUE & ACTION	QTY	AGENCY
1	***9920	***0046	TH1N	SIDE GRIP (C) (1) MOT	1	PSD
2	***6910	***3192	TH1N	SPEAKER MID (C) (1) MOT	1	PSD
3	***9220	***9008	TH1N	ACOVER (C) (1) MOT + BCOVER (C) (1) MOT + UIFRAME (C) (1) MOT + BUTTONPTT (R) (1) MOT	1	PSD
4	-	*	TH1N	BATTERY3180 (C) (5) MOT	5	PSD
5	-	*	TH1N	CHARGER12 (C) (2) MOT	2	PSD
6	***4390	*	TH1N	CHARGER12 (C) (1) MOT	1	PSD
7	***9670	*	SRG3900 CARKIT	DISMANTLE (D) (1)	1	PSD

Split Format (Airbus / Sepura / Hytera) — Materials Summary

AIRBUS	SEPURA	HYTERA
AIRBUS TH1N ACOVER (MOT) = 1 BATTERY3180 (MOT) = 5 BCOVER (MOT) = 1 BUTTONPTT (MOT) = 1 CHARGER12 (MOT) = 3 SIDE GRIP (MOT) = 1 SPEAKER MID (MOT) = 1 UIFRAME (MOT) = 1	SEPURA SRG CARKIT DISMANTLE (D) = 1	NO ENTRY

Split Format (Airbus / Sepura / Hytera) — Device Summary

AIRBUS	SEPURA	HYTERA
AIRBUS TH1N 1. MAINTENANCE = 11 TOTAL = 11	SEPURA CARKIT 1. DISMANTLE = 1 TOTAL = 1	NO ENTRY