

Г	1	2			3		4	
A	II version	III version	VI ve	ersion	V version			A
В	1. Changed the fuse symbol 2. Changed components style 3. Replaced MCU pins 4. There were 3 different capacitor symbols on schematics, now 1 5. Changed VCC and 3.3V symbols 6. Placed ports and changed some net labels 7. Added datasheet links under parameters 8. In II version used LTC3649 and LT3080 for feedback and power control 9. Maybe right now the old sensing sheet is useless?	Annotated schematics Changed designators to standard designators Changed coltage and current sensing logic Added on-board connectors for components that will be connected with wires Fixed all errors on schematic Recalculated all of the resistor values All of power pins now have their voltage inside their net name 8.	output&ext-memodules and or 2. Changed X2 3. Changed J1 4. Changed 3.5 5. Changed 4 po 6. Fixed USB of MCU 7. Took away V 8. Changed 18	caps value designator V and 5V LDOs sition of USB connector onnector circuit to program //BUS cap k resistors to 9k verse protection diode between	1. Added comments to comblock 2. Fixed R2 and R3 values 3. Calculated the current of components - added them a 4. Added crystal caps calcu 5. Modified MCU symbol 6. Modified the layout of cinputs on the left hand side 7. Removed two different I one 8. modified J5 and added 2 250mA output and 5V outp 9. Modified connections of 10. Modified U11, U12, U1 (LT3080) 11. Modified uninformative 12. Took out unnecessary or	from 22k to 22R 5V and 3.3V s blue notes lations omponents to keep OACs - now using OR resistor to have ut UT 3 symbols e nets		В
С					12. Took out uniecessal y o	imponents		С
D	I	2			Title Number)23 Sh	Revision eet of awn By:	D









