Service Schematics

NOKIA 2310

RM-189

Introduction

Important:

This document is intended for use by authorized service centers only.

"Service Schematics" was created with focus on customer care.

The purpose of this document is to provide further technical repair information for NOKIA mobile phones on Level 3/4 service activities.

It contains additional information such as e.g. "Component finder",

"Frequency band table" or "Antenna switch table".

The "Signal overview" page gives a good and fast overview about the most important signals and voltages on board.

Saving process time and improving the repair quality is the aim of this document. It is to be used additionaly to the service manual and other training or service information such as Service Bulletins.

All measurements were made using following equipment:

Nokia repair SW : Phoenix version 2006.04.6.136

Oscilloscope : Fluke PM 3380A/B

Spectrum Analyzer : Advanced R3162 with an analog probe

RF-Generator/GSM Tester: Rhode & Schwarz CMU 200

Multimeter : Fluke 73 Series II

Tabel of content	
Frontpage	1
UI & Audio	2
UEM, UPP & Flash memory	3
RF-part	4
Signal overview	5
Component finder	6

While every endeavour has been made to ensure the accuracy of this document, some errors may exist. If the reader finds any errors, NOKIA shall be notified in writing.


Please send E-Mail to: training.sace@nokia.com


Copyright © NOKIA


This material, including documentation and any related computer programs is protected by copyright, controlled by NOKIA. All rights are reserved. Copying, including reproducing, modifying, storing, adapting or translating any or all of this material requires the prior written consent of NOKIA. This material also contains confidential information, which may not be disclosed to others whitout the prior written consent of NOKIA.


Customer Care / Service Operations / Content Creation Team Confidential Copyright © 2006 NOKIA Only for training purposes


Version: 1.0 | 29.05.2006 | 2310 | Board version: 2aa_50a | Frontpage | Page 1(6)














Customer Care / Service Operations / Content Creation Team Confidential Copyright © 2006 NOKIA Only for training purposes

Version: 1.0

29.05.2006

2310 | B

Board version: 2aa_50a |

Signal overview

В		(2405	DE	(772)	בז	D21F0	MZ
	0.7	C2405	P5	C7726	J2	R2159	N7
B2200	07	C2700	R4	C7727	K2	R2160	L6
B7600	K5	C2880	04	C7728	K2	R2171	N8
C		C2881	P3	D		R2200	P6
C2000	G3	C2882	P3	D2200	05	R2202	М7
C2001	G2	C2883	02	D2800	03	R2203	M7
C2002	G4	C2884	02	D3000	М3	R2204	M6
C2003	S 5	C2885	Р3	F		R2205	М6
C2004	R5	C2886	P3	F2000	T7	R2206	М7
C2005	R5	C2887	02	Н	-	R2207	14
C2006	R5	C2900	K7	H2400	C3	R2400	U5
	_			H2400 C3			
C2007	S7	C3030	N2	_	77	R2401	06
C2008	R4	C3031	N2	L2000	T7	R2406	02
C2009	R4	C3032	N2	L2001	R3	R2407	P2
C2010	R5	C6157	R6	L2002	R4	R2408	P2
C2011	S3	C6158	R6	L2005	R6	R2409	T4
C2012	R4	C6159	Q7	L2170	S3	R2700	P4
C2013	R3	C6162	Q6	L2180	M7	R2900	K7
C2017	G5	C6163	R6	L2181	M7	R3030	02
(2151	N7	C6165	08	L2182	В6	R6110	Q8
(2152	S3	C6170	R7	L2183	B6	R6159	R6
C2153	B6	C6176	R7	12400	U6	R6160	R6
(2154	В7		R7	L6156			K0
CLIJ!		C6178	-		Q6	R7605	_
C2155	N6	C6179	R7	L6176	R7	R7606	H7
C2157	80	C7604	16	L7602	17	R7609	К6
C2159	N7	C7607	17	L7603	17	R7610	M5
C2161	N8	C7610	18	L7604	I6	R7611	M5
C2164	N6	C7611	17	L7605	16	R7615	Н8
C2165	N7	C7612	17	L7607	Н6	R7616	Н7
(2171	N8	C7613	17	М		R7617	Н7
C2180	N7	C7614	17	M2000 G6		R7619	18
(2181	M7	C7620	у. К7	N	uo	R7630	K6
(2182	M7	C7623	17	N2150	М7	R7631	K7
			,				_
C2200	07	C7624	<u>18</u>	N2160	L7	R7632	K6
C2202	07	C7625	J6	N2400	T6	R7633	K2
C2203	07	C7627	J5	N6156	Q7	R7635	K2
C2204	P5	C7628	J5	N7600	Ј7	R7663	К8
C2205	P5	C7630	К6	N7700	J3	R7700	15
C2208	P4	C7631	D3	R		R7701	I5
C2220	M7	C7634	I7	R2000	G3	R7703	T 5
(2222	Р7	C7635	К6	R2001	Q3	R7704	КЗ
(2223	07	C7636	К6	R2002	R5	R7705	K3
	_		_				_
(2225	M6	C7637	K2	R2003	R5	R7706	K3
(2226	P7	C7638	K2	R2004	R5	R7707	15 15
C2227	M6	C7639	<u>J7</u>	R2005	S5	R7709	I5
C2230	07	C7641	J7	R2006	R5	R7711	J4
C2233	07	C7643	К6	R2007	R4	R7714	J2
C2235	M7	C7644	J7	R2008	S4	R7720	K4
C2236	M5	C7645	I7	R2009	R4	R7732	K2
C2237	M5	C7655	I5	R2010	S3	R7733	K2
(2239	P5	C7656	J5	R2011	R4	V	
C2240	М6	C7657	K7	R2013	R5	V2000	S7
(2241	M6	C7658	J7	R2020	R5	V2160	L6
(2242	M6	C7659	I6	R2027	R5	V2400	U5
	P6	C7668	I6		_	V2400 V2401	U3
	rn I	(1000	_	R2068	S2		
C2261		(7(()		R2069	S2	V7600	K6
C2261 C2262	Q8	C7669	K8	D24-4	c- '		
C2261 C2262 C2263	Q8 R8	C7700	К3	R2070	S2	Х	_
C2261 C2262 C2263 C2287	Q8	C7700 C7701	K3	R2150	S2 N7	X2005	G3
C2261 C2262 C2263	Q8 R8	C7700	К3	R2150 R2151			G3 Q4
C2261 C2262 C2263 C2287	Q8 R8 M5	C7700 C7701	K3	R2150	Ν7	X2005	_
C2261 C2262 C2263 C2287 C2330	Q8 R8 M5 G2	C7700 C7701 C7702	K3 K3 K4	R2150 R2151	N7 L7	X2005 X2700	Q4
C2261 C2262 C2263 C2287 C2330 C2331	Q8 R8 M5 G2 P5	C7700 C7701 C7702 C7711 C7712	K3 K3 K4 I2	R2150 R2151 R2152 R2153	N7 L7 N7	X2005 X2700 Z Z2400	Q4 Q3
C2261 C2262 C2263 C2287 C2330 C2331 C2332 C2400	Q8 R8 M5 G2 P5 P5	C7700 C7701 C7702 C7711 C7712 C7713	K3 K4 I2 I4	R2150 R2151 R2152 R2153 R2154	N7 L7 N7 N7	X2005 X2700 Z Z2400 Z7600	Q4 Q3 H6
C2261 C2262 C2263 C2287 C2330 C2331 C2332 C2400 C2401	Q8 R8 M5 G2 P5 P5 U4 U5	C7700 C7701 C7702 C7711 C7712 C7713 C7714	K3 K4 I2 I4 I2 K3	R2150 R2151 R2152 R2153 R2154 R2155	N7 L7 N7 N7 N7 L6	X2005 X2700 Z Z2400 Z7600 Z7602	Q4 Q3 H6 H7
C2261 C2262 C2263 C2287 C2330 C2331 C2332 C2400	Q8 R8 M5 G2 P5 P5	C7700 C7701 C7702 C7711 C7712 C7713	K3 K4 I2 I4	R2150 R2151 R2152 R2153 R2154	N7 L7 N7 N7	X2005 X2700 Z Z2400 Z7600	_

