
SMD Soldering



Center part onto pad Continue heating 1-2s

