

High speed data offload

To offload data over a glider's hardware serial link:

1. Connect your computer to wall power.
2. Disable sleep mode on your computer.
3. Connect the hardware serial line with a USB-Serial dongle capable of running 921,600 baud to your computer.
4. Start up your serial terminal emulator at 115,200 baud, I use ZOC, Tera Term will work.
5. Power up the glider and **control-C** to Gliderdos.
6. Enter **use - iridium**
7. Enter **lab_mode** on
8. Enter **hs on** and change your terminal emulator to 921,600 baud, and type **y**
9. Set the download directory of your terminal emulator.
10. Enter **put u_max_time_in_gliderdos -1**
11. Enter **put u_max_num_files_to_xmit_at_once -1**
12. You can either organize the files into directories before or after the transfer
 - Generally, I think it is easier to do before.
13. Enter **zs config/*.***
 - Once those files are transferred move them to the flight/config directory on your local machine to keep them organized.
14. Do the same with **config/*.* state/cache/*.* sentlogs/*.* logs/*.***
15. Enter **szs config/*.* state/cache/*.* sentlogs/*.* logs/*.*** to transfer files from the science computer.
16. Enter send *.*.

The zs, szs, and send commands will take a while.