





To polish Hulls we use 600 Grit sand paper from Norton Abrasives as shown to the left.




You'll want to cut the sand paper into small pieces, I used about 2 x 2 inches



Next, the polishing area must be clean of any O-Lube or debris, recommend cleaning with alcohol wipes

Before polishing you will need to wet the sand paper, and wet the area of the hull you want to polish as shown below





Lightly polish the hull, going around the entire surface of the O-ring mating surface.

If you can still feel the scratch, polish the problem area in a circular motion and then re-polish the whole O-ring mating surface.

When you are done you will have residue on the sand paper as shown to the left.



The O-ring mating surface will also have some residue. This will need to be cleaned with an alcohol wipe. After polishing it is a good idea to re grease with O-lube and run a helium/vacuum test.

If the scratch is still a problem, recommend sending to TWR for Hull Repair

Note: theres a limit on how many times a hull can be polished/reworked so only polish if necessary