PDS calibration using drunc

Parameter scans and synchronized acquisition


Manuel Arroyave

20 October 2026



Fermilab

Calibration scans a grid of settings




Each point: apply settings, acquire data.

Also: trim, trigger thresholds, LED widths / delay.

Select wavelength, mask, pulse mode / burst.


Record rate, window, event count.

Drive DAPHNE and the calibration box in sync



Verify LED-to-ADC delay and pulse counts.

PDS needs a repeatable fast calibration loop in drunc



Expose calibration transitions in drunc; reconfigure between runs.