






Physical System

wheel with motor





Connections


MPV-6050 to I²C



Have to set up motor driver to MCU connection.
Use PWM

Real Params





683 g

① wheel : 33 g

$$889 - 683 = 206 \text{ g} - \text{motors}$$

Power bank : 153 g

Motor driver : 26 g

STM Board : 36 g




Breadboard : 107 g

Cart mass:

$$206 \text{ g} + 2 \cdot 33 \text{ g} = 206 \text{ g} + 66 \text{ g} = 272 \text{ g}$$

Robot mass:


$$683 \text{ g} + 153 \text{ g} + 26 \text{ g} + 36 \text{ g} + 107 \text{ g} = 1005 \text{ g}$$



$$167 + 8 = 175 \cdot 2 = 350$$

$$683 - 350 = 333 + 19 \cdot 2 = 333 + 38 = 371$$

$$1005 - 350 = 765$$



Dims

Motor aksl: $2,3 \times 9$ mm

Converter: 65×36 mm

Batteri: 72×34 mm

Motor driver: 43×43 mm

MCU: 80×68 mm

Bread board: 164×54 mm

