Change Order Report For Project ResearchProject_V3.PrjPcb And ResearchProject_V3.Pr

Action	Object	Change Document	Status
Add Components			
Add	C26	To ResearchProject_V5.PcbDoc	Footprint Not Found CAP0603
Add	C27	To ResearchProject_V5.PcbDoc	Footprint Not Found CAP0603
Add	C28	To ResearchProject_V5.PcbDoc	Footprint Not Found CAP0603
Add	C29	To ResearchProject_V5.PcbDoc	Footprint Not Found CAP0603
Add	C36	To ResearchProject_V5.PcbDoc	Footprint Not Found CAP0603
Add	C61	To ResearchProject_V5.PcbDoc	Footprint Not Found CAP0603
Add	C62	To ResearchProject_V5.PcbDoc	Footprint Not Found CAP0603
Add	C63	To ResearchProject_V5.PcbDoc	Footprint Not Found CAP0603
Add	C64	To ResearchProject_V5.PcbDoc	Footprint Not Found CAP0603
Add Pins To Nets			
Add	C26-1 to 3V3	In ResearchProject_V5.PcbDoc	Unknown Pin: Pin C26-1
Add	C26-2 to GND	In ResearchProject_V5.PcbDoc	Unknown Pin: Pin C26-2
Add	C27-1 to 3V3	In ResearchProject_V5.PcbDoc	Unknown Pin: Pin C27-1
Add	C27-2 to GND	In ResearchProject_V5.PcbDoc	Unknown Pin: Pin C27-2
Add	C28-1 to 3V3	In ResearchProject_V5.PcbDoc	Unknown Pin: Pin C28-1
Add	C28-2 to GND	In ResearchProject_V5.PcbDoc	Unknown Pin: Pin C28-2
Add	C29-1 to 3V3	In ResearchProject_V5.PcbDoc	Unknown Pin: Pin C29-1
Add	C29-2 to GND	In ResearchProject_V5.PcbDoc	Unknown Pin: Pin C29-2
Add	C36-1 to VREGOUT_NET	In ResearchProject_V5.PcbDoc	Unknown Pin: Pin C36-1
Add	C36-2 to GND	In ResearchProject_V5.PcbDoc	Unknown Pin: Pin C36-2
Add	C61-1 to VREGOUT_NET	In ResearchProject_V5.PcbDoc	Unknown Pin: Pin C61-1
Add	C61-2 to GND	In ResearchProject_V5.PcbDoc	Unknown Pin: Pin C61-2
Add	C62-1 to VREGOUT_NET	In ResearchProject_V5.PcbDoc	Unknown Pin: Pin C62-1
Add	C62-2 to GND	In ResearchProject_V5.PcbDoc	Unknown Pin: Pin C62-2
Add	C63-1 to VREGOUT_NET	In ResearchProject_V5.PcbDoc	Unknown Pin: Pin C63-1
Add	C63-2 to GND	In ResearchProject_V5.PcbDoc	Unknown Pin: Pin C63-2
Add	C64-1 to VREGOUT_NET	In ResearchProject_V5.PcbDoc	Unknown Pin: Pin C64-1
Add	C64-2 to GND	In ResearchProject_V5.PcbDoc	Unknown Pin: Pin C64-2
Add Component Class Members			
Add	C26 to ResearchProject_V3_schematic	In ResearchProject_V5.PcbDoc	Failed to add class member : Com
Add	C27 to ResearchProject_V3_schematic	In ResearchProject_V5.PcbDoc	Failed to add class member : Com
Add	C28 to ResearchProject_V3_schematic	In ResearchProject_V5.PcbDoc	Failed to add class member : Com
Add	C29 to ResearchProject_V3_schematic	In ResearchProject_V5.PcbDoc	Failed to add class member : Com
Add	C36 to ResearchProject_V3_schematic	In ResearchProject_V5.PcbDoc	Failed to add class member : Com
Add	C61 to ResearchProject_V3_schematic	In ResearchProject_V5.PcbDoc	Failed to add class member : Com
Add	C62 to ResearchProject_V3_schematic	In ResearchProject_V5.PcbDoc	Failed to add class member : Com
Add	C63 to ResearchProject_V3_schematic	In ResearchProject_V5.PcbDoc	Failed to add class member : Com
Add	C64 to ResearchProject_V3_schematic	In ResearchProject_V5.PcbDoc	Failed to add class member : Com