

U.S. SUZUKI MOTOR CORPORATION

November 20, 1985

Administrator

01-22-NIIB-2225

National Highway Traffic Safety Administration 400 Seventh St., S.W. Washington, DC 20590

Attn: VIN Coordinator

Gentlemen:

Attached are three copies each of our Revision and Appendix Log and page 31 of Appendix I to Suzuki Engineering Standards (SES-N4009) Vehicle Identification Number.

As mentioned in our original correspondence to your agency, dated April 2, 1980, Appendix I supplements the second section "Vehicle Descriptor Section" of Suzuki Engineering Standards (SES-N4009) Vehicle Identification Number. This information will assist in providing your agency with a clear explanation of the five characters contained in the second section of the Vehicle Identification Numbers that will be affixed to our products.

This submission respresents the addition of the GSX-R1100 model motorcycle to our product line.

Sincerely,

U.S. SUZUKI MOTOR CORP.

Frederic M. Petler Head, Administration

Government Relations Department

FMP:bf Enclosures



CABLE ADDRESS
"SUZUKI HAMAMATSU"
Tel. Homometiu (47) 1111

Established: 1920

P. O. Box 116. Hamamatsu. Japan. TOKYO BRANCH No. 2-8, 2-chome. Higgshi-Shinbashi, Minoto-tu, Tokyo Tel. (432) 729

Your	ref
Our	

TELEX NO. 425-12 SUZUKI HAM

SUZUKI ENGINEERING STANDARDS
(SES-N4009)

Vehicle Identification Number

For

United States of America and Canada

REVISION AND APPENDIX LOG

Appendix I	1-28-83	pg. 22
Appendix I	2-01-83	pg. 23
Appendix I	12-13-83	pg. 24
Appendix I	4-17-84	pg. 25
Appendix I	6-29-84	pg. 26
Appendix I	7-10-84	pg. 27
Appendix I	8-07-84	pg. 28
Appendix I	2-27-85	pg. 29
Appendix I	10-29-85	pg. 30
Appendix I	11-20-85	pg. 31



SUZUKI MOTOR CO., LTD.

CABLE ADDRESS
"SUZUKI HAMAMATSU"

Tol. Homomotru (47) 1111

TELEX NO. 425-12 SUZUKI HAM

Established : 1720

P. O. Box 116. Hamamatsu, Japan.

TOKYO BRANCH No. 2-8, 2-chome. Migeshi-Shinbashi, Minoto-ku, Tokyo Tel. (432) 729

Your	ref
Out	ml

SUZUKI ENGINEERING STANDARDS

(SES-N4009)

Vehicle Identification Number

For

United States of America and Canada

REVISION AND APPENDIX LOG

Appendix I	1-28-83	pg. 22
Appendix I	2-01-83	pg. 23
Appendix I	12-13-83	pg. 24
Appendix I	4-17-84	pg. 25
Appendix I	6-29-84	pg. 26
Appendix I	7-10-84	pg. 27
Appendix I	8-07-84	pg. 28
Appendix I	2-27-85	pg. 29
Appendix I	10-29-85	pg. 30
Appendix I	11-20-85	pg. 31



SUZUKI MOTOR CO., LTD.

CABLE ADDRESS

"SUZUKI HAMAMATSU"

Tel. Hemometru (47) 1111

TELEX NO. 425-12 SUZUKI HAM

Established : 1920

P. O. Box 116, Hamamatsu, Japan.

TOKYO BRANCH
No. 2-8, 2-chome
Migashi-Shinbashi,
Minato-Lu. Tokyo
Tel. (432) 729

Your	101,
Out	

SUZUKI ENGINEERING STANDARDS

(SES-N4009)

Vehicle Identification Number

For

United States of America and Canada

REVISION AND APPENDIX LOG

Appendix I	1-28-83	pg. 22
Appendix I	2-01-83	pg. 23
Appendix I	12-13-83	pg. 24
Appendix I	4-17-84	pg. 25
Appendix I	6-29-84	pg. 26
Appendix I	7-10-84	pg. 27
Appendix I	8-07-84	pg. 28
Appendix I	2-27-85	pg. 29
Appendix I	10-29-85	pg. 30
Appendix I	11-20-85	pg. 31

APPENDIX I TO SUZUKI ENGINEERING STANDARDS (SES-N4009) VEHICLE IDENTIFICATION NUMBER

Page 31 November 20, 1985

Second Section

INFORMATION TO DECIPHER V.I.N.

MODEL	2ND SECTION OF VIN		1705	DICDI ACEMENT (CC)	H.P.	ENGINE TYPE
	V1 1211	TYPE OF M/C	LINE	DISPLACEMENT (CC)		
GSX-R1100	G U 7 4 A	Touring (I)	GSX-R1100	1052	130	4 cycle, 4 cylindo
					1	
						l. 1
						1

APPENDIX I TO SUZUKI ENGINEERING STANDARDS (SES-N4009) VEHICLE IDENTIFICATION NUMBER

Page 31 November 20, 1985

Second Section

INFORMATION TO DECIPHER V.I.N.

MODEL	2ND SECTION OF VIN	TVDF OF M/C	LINE	DISPLACEMENT (CC)	н.Р.	ENGINE TYPE
CV D1100	G U 7 4 A	TYPE OF M/C Touring (I)	GSX-R1100	1052	130	4 cycle, 4 cylind
SX-R1100	90747	, our,				
					.	

APPENDIX I TO JUZUKI ENGINEERING STANDARDS (SES-N4009) VEHICLE IDENTIFICATION NUMBER

Page 31 November 20, 1985

Second Section

INFORMATION TO DECIPHER V.I.N.

MODEL	2ND SECTION OF VIN	TYPE OF M/C	LINE	DISPLACEMENT (CC)	H.P.	ENGINE TYPE
SX-R1100	G U 7 4 A	Touring (I)	GSX-R1100	1052	130	4 cycle, 4 cylind