

Automotive Safety Office Environmental and Safety Engineering

August 5, 2005

David Coleman
Office of Vehicle Safety Compliance
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590

Dear Mr. Coleman:

Subject: Gross Vehicle Weight Ratings Reclassification for Certain 2005 Model Year F-350 Superduty Vehicles

In January and February of 2005 Ford Motor Company (Ford) produced 429 complete 2005 model year F-350 Superduty pick-up trucks with a Class 3 (10,001 – 14,000 pounds) gross vehicle weight rating (GVWR) for Servicemaster Consumer Services, headquartered in Memphis, Tennessee. Ford will be reclassifying the GVWR on these vehicles to Class H (9,001 – 10,000 pounds) to make them equivalent to subsequently produced vehicles with similar content, at the request of the fleet.

As directed in your July 8, 2005, e-mail to a member of my staff, Ford is providing the agency a list of the vehicle identification numbers for these 429 vehicles in the attached document.

If there are any questions regarding this VIN information, please contact me.

Sincerely,

R. A. Nevi

Assistant Director

T. A. Their

Global Automotive Safety Compliance

Attachment

No.	VIN
1	1FTWF30P55ED02563
2	1FTWF30P75EB83611
3	1FTWF30P05EB83613
4	1FTWF30P45EC01501
5	1FTWF30P35ED02562
6	1FTWF31P25EC15167
7	1FTSX31P75ED34103
8	1FTSX31P95ED34104
9	1FTSX31P05ED34105
10	1FTWF31P25ED02566
11	1FDWW30PX5EC01496
12	1FDWW30P15EC01497
13	1FTWW30P85ED12682
14	1FTWW30P75ED02564
15	1FTWW30P95ED02565
16	1FTWW30P65ED12681
17	1FTWX30P05ED34110
18	1FTWX30P45ED34109
19	1FTWX30P25ED34108
20	1FTWX31P85EC24906
21	1FTWF305X5EA76390
22	1FTWF30515EA76360
23	1FTWF30535EA76361
24	1FTWF30595EA76364
25	1FTWF30505EA76365
26	1FTWF30545EA76367
27	1FTWF30565EA76368
28	1FTWF30585EA76369
29	1FTWF30565EA76371
30	1FTWF305X5EA76292
31	1FTWF30515EA76147
32	1FTWF30575EA76153
33	1FTWF30565EA76158
34	1FTWF30585EA76159
35	1FTWF30565EA76161
36	1FTWF305X5EA76163
37	1FTWF30515EA76164
38	1FTWF30535EA76165
39	1FTWF30595EA76168
40	1FTWF30505EA76172
41	1FTWF30535EA76179
42	1FTWF30545EA76191
43	1FTWF30585EA76193
44	1FTWF30525EA76223
45	1FTWF30585EA76226
46	1FTWF30505EA76446

No.	VIN
47	1FTWF30515EA76309
48	1FTWF30545EA76319
49	1FTWF30515EA76410
50	1FTWF30535EA76411
51	1FTWF30545EA76160
52	1FTWF30585EA76162
53	1FTWF30505EA76169
54	1FTWF30575EA76170
55	1FTWF30585EA76176
56	1FTWF30515EA76178
57	1FTWF305X5EA76180
58	1FTWF30535EA76182
59	1FTWF30565EA76192
60	1FTWF30535EA76196
61	1FTWF30555EA76197
62	1FTWF30595EA76199
63	1FTWF30535EA76201
64	1FTWF30555EA76202
65	1FTWF30575EA76203
66	1FTWF30595EA76204
67	1FTWF30505EA76205
68	1FTWF30525EA76206
69	1FTWF30545EA76210
70	1FTWF305X5EA76213
71	1FTWF30535EA76215
72	1FTWF30555EA76216
73	1FTWF30575EA76217
74	1FTWF30595EA76218
75	1FTWF30575EA76220
76	1FTWF30595EA76221
77	1FTWF30505EA76222
78	1FTWF30525EA76223
79	1FTWF30565EA76225
80	1FTWF30515EA76228
81	1FTWF30535EA76229
82	1FTWF305X5EA76230
83	1FTWF30515EA76231
84	1FTWF30535EA76232
85	1FTWF30555EA76233
86	1FTWF30575EA76234
87	1FTWF30505EA76236
88	1FTWF30545EA76238
89	1FTWF30565EA76239
90	1FTWF30545EA76241
91	1FTWF30565EA76242
92	1FTWF30585EA76243

No.	VIN
93	1FTWF305X5EA76244
94	1FTWF30515EA76245
95	1FTWF30535EA76246
96	1FTWF30555EA76247
97	1FTWF30595EA76249
98	1FTWF30555EA76250
99	1FTWF30575EA76251
100	1FTWF30595EA76252
101	1FTWF30505EA76253
102	1FTWF30525EA76254
103	1FTWF30545EA76255
104	1FTWF30585EA76257
105	1FTWF305X5EA76258
106	1FTWF30585EA76260
107	1FTWF30515EA76262
108	1FTWF30535EA76263
109	1FTWF30555EA76264
110	1FTWF30575EA76265
111	1FTWF30595EA76266
112	1FTWF30505EA76267
113	1FTWF30525EA76268
114	1FTWF30545EA76269
115	1FTWF30505EA76270
116	1FTWF30525EA76271
117	1FTWF30545EA76272
118	1FTWF30565EA76273
119	1FTWF30585EA76274
120	1FTWF305X5EA76275
121	1FTWF30515EA76276
122	1FTWF30535EA76277
123	1FTWF30555EA76278
124	1FTWF30575EA76279
125	1FTWF30535EA76280
126	1FTWF30555EA76281
127	1FTWF30575EA76282
128	1FTWF30595EA76283
129	1FTWF30505EA76284
130	1FTWF30525EA76285
131	1FTWF30545EA76286
132	1FTWF30565EA76287
133	1FTWF30585EA76288
134	1FTWF305X5EA76289
135	1FTWF30565EA76290
136	1FTWF30585EA76291
137	1FTWF30515EA76293
138	1FTWF30535EA76294

No.	VIN
139	1FTWF30555EA76295
140	1FTWF30575EA76296
141	1FTWF30595EA76297
142	1FTWF30505EA76298
143	1FTWF30525EA76299
144	1FTWF30555EA76300
145	1FTWF30575EA76301
146	1FTWF30595EA76302
147	1FTWF30505EA76303
148	1FTWF30525EA76304
149	1FTWF30545EA76305
150	1FTWF30565EA76306
151	1FTWF30585EA76307
152	1FTWF305X5EA76308
153	1FTWF30585EA76310
154	1FTWF305X5EA76311
155	1FTWF30515EA76312
156	1FTWF30535EA76313
157	1FTWF30555EA76314
158	1FTWF30575EA76315
159	1FTWF30595EA76316
160	1FTWF30505EA76317
161	1FTWF30525EA76318
162	1FTWF30505EA76320
163	1FTWF30525EA76321
164	1FTWF30545EA76322
165	1FTWF30565EA76323
166	1FTWF305X5EA76325
167	1FTWF30515EA76326
168	1FTWF30535EA76327
169	1FTWF30555EA76328
170	1FTWF30575EA76329
171	1FTWF30535EA76330
172	1FTWF30555EA76331
173	1FTWF30575EA76332
174	1FTWF30595EA76333
175	1FTWF30505EA76334
176	1FTWF30525EA76335
177	1FTWF30545EA76336
178	1FTWF30565EA76337
179	1FTWF30585EA76338
180	1FTWF305X5EA76339
181	1FTWF30565EA76340
182	1FTWF30585EA76341
183	1FTWF305X5EA76342
184	1FTWF30515EA76343

No.	VIN
185	1FTWF30535EA76344
186	1FTWF30555EA76345
187	1FTWF30575EA76346
188	1FTWF30595EA76347
189	1FTWF30505EA76348
190	1FTWF30525EA76349
191	1FTWF30595EA76350
192	1FTWF30505EA76351
193	1FTWF30525EA76352
194	1FTWF30545EA76353
195	1FTWF30565EA76354
196	1FTWF30585EA76355
197	1FTWF305X5EA76356
198	1FTWF30515EA76357
199	1FTWF30535EA76358
200	1FTWF30555EA76359
201	1FTWF30515EA76360
202	1FTWF30535EA76361
203	1FTWF30555EA76362
204	1FTWF30575EA76363
205	1FTWF30595EA76364
206	1FTWF30505EA76365
207	1FTWF30525EA76366
208	1FTWF30545EA76367
209	1FTWF30565EA76368
210	1FTWF30585EA76369
211	1FTWF30545EA76370
212	1FTWF30565EA76371
213	1FTWF30585EA76372
214	1FTWF305X5EA76373
215	1FTWF30515EA76374
216	1FTWF30535EA76375
217	1FTWF30555EA76376
218	1FTWF30575EA76377
219	1FTWF30595EA76378
220	1FTWF30505EA76379
221	1FTWF30575EA76380
222	1FTWF30595EA76381
223	1FTWF30505EA76382
224	1FTWF30515EA76388
225	1FTWF30525EA76383 1FTWF30545EA76384
226	1FTWF30545EA76384 1FTWF30565EA76385
227	1FTWF30565EA76385 1FTWF30585EA76386
228	1FTWF305X5EA76386
230	1FTWF305X5EA76387
230	TE IME 30333EW / 0303

No.	VIN
231	1FTWF30515EA76391
232	1FTWF30535EA76392
233	1FTWF30555EA76393
234	1FTWF30575EA76394
235	1FTWF30595EA76395
236	1FTWF30505EA76396
237	1FTWF30525EA76397
238	1FTWF30545EA76398
239	1FTWF30565EA76399
240	1FTWF30595EA76400
241	1FTWF30505EA76401
242	1FTWF30525EA76402
243	1FTWF30545EA76403
244	1FTWF30565EA76404
245	1FTWF30585EA76405
246	1FTWF305X5EA76406
247	1FTWF30515EA76407
248	1FTWF30535EA76408
249	1FTWF30555EA76409
250	1FTWF30555EA76412
251	1FTWF30575EA76413
252	1FTWF30595EA76414
253	1FTWF30505EA76415
254	1FTWF30525EA76416
255	1FTWF30545EA76417
256	1FTWF30565EA76418
257	1FTWF30585EA76419
258	1FTWF30545EA76420
259	1FTWF30565EA76421
260	1FTWF30585EA76422
261	1FTWF305X5EA76423
262	1FTWF30515EA76424
263	1FTWF30535EA76425
264	1FTWF30555EA76426
265	1FTWF30575EA76427
266	1FTWF305X5EA77023
267	1FTWF30595EA76428
268	1FTWF30505EA76429
269	1FTWF30575EA76430
270	1FTWF30595EA76431
271	1FTWF30505EA76432
272	1FTWF30525EA76433
273	1FTWF30545EA76434
274	1FTWF30565EA76435
275	1FTWF30585EA76436
276	1FTWF305X5EA76437

277 1FTWF30515EA7643 278 1FTWF30535EA7643 279 1FTWF305X5EA7644 280 1FTWF30515EA7644 281 1FTWF30535EA7644 282 1FTWF30555EA7644 283 1FTWF30545EC0429 284 1FTWF30565EC0429 285 1FTWF30P85EC0150 286 1FTWW30P75ED3410 287 1FTWX30T25ED3411	Ω
279 1FTWF305X5EA7644 280 1FTWF30515EA7644 281 1FTWF30535EA7644 282 1FTWF30555EA7644 283 1FTWF30545EC0429 284 1FTWF30565EC0429 285 1FTWF30P85EC0150 286 1FTWW30P75ED3410	J
280 1FTWF30515EA7644 281 1FTWF30535EA7644 282 1FTWF30555EA7644 283 1FTWF30545EC0429 284 1FTWF30565EC0429 285 1FTWF30P85EC0150 286 1FTWW30P75ED3410	9
281 1FTWF30535EA7644 282 1FTWF30555EA7644 283 1FTWF30545EC0429 284 1FTWF30565EC0429 285 1FTWF30P85EC0150 286 1FTWW30P75ED3410	0
282 1FTWF30555EA7644 283 1FTWF30545EC0429 284 1FTWF30565EC0429 285 1FTWF30P85EC0150 286 1FTWW30P75ED3410	1
283 1FTWF30545EC0429 284 1FTWF30565EC0429 285 1FTWF30P85EC0150 286 1FTWW30P75ED3410	2
284 1FTWF30565EC0429 285 1FTWF30P85EC0150 286 1FTWW30P75ED3410	3
285 1FTWF30P85EC0150 286 1FTWW30P75ED3410	7
286 1FTWW30P75ED3410	8
 	3
287 1FTWX30T25ED3411	7
	1
288 1FTWF30PX5EC0149	9
289 1FTWF30P55EC0149	1
290 1FTWF30P95EC0149	3
291 1FTWF30P75EC0149	2
292 1FTWF30P25EC0150	0
293 1FTWF32P25EB9213	3
294 1FTWF32P95EB9212	8
295 1FTWF32P75EB9213	0
296 1FTWF32P95EB9213	1
297 1FTWF32P75EB9212	7
298 1FTWF32P05EB9212	9
299 1FDWF31P55EC0149	В
300 1FTWF30P95EB83593	3
301 1FTWF30P95EB8313	9
302 1FTWF30P55EB8314)
303 1FTWF30P65EB8352	l
304 1FTWF30P85EB83522	2
305 1FTWF30PX5EB83523	3
306 1FTWF30P15EB83524	1
307 1FTWF30P35EB8352	5
308 1FTWF30P55EB83526	5
309 1FTWF30P75EB8352	7
310 1FTWF30P95EB83528	3
311 1FTWF30P05EB83529	9
312 1FTWF30P75EB83530)
313 1FTWF30P95EB8353	l l
314 1FTWF30P05EB83532	2
315 1FTWF30P25EB83533	3
316 1FTWF30P45EB83534	1
317 1FTWF30P65EB8353	5
318 1FTWF30P85EB83536	<u> </u>
319 1FTWF30PX5EB8353	7
320 1FDWF30P35EB8356	7
321 1FDWF30P55EB83568]
322 1FDWF30P75EB83569	}

No.	VIN
323	1FDWF30P35EB83570
324	1FDWF30P55EB83571
325	1FTWF30P15EB83572
326	1FTWF30P35EB83573
327	1FTWF30P55EB83574
328	1FTWF30P75EB83575
329	1FTWF30P95EB83576
330	1FTWF30P05EB83577
331	1FTWF30P25EB83578
332	1FTWF30P45EB83579
333	1FTWF30P05EB83580
334	1FTWF30P25EB83581
335	1FTWF30P45EB83582
336	1FTWF30P65EB83583
337	1FTWF30P85EB83584
338	1FTWF30PX5EB83585
339	1FTWF30P15EB83586
340	1FTWF30P35EB83587
341	1FTWF30P55EB83588
342	1FTWF30P75EB83589
343	1FTWF30P35EB83590
344	1FTWF30P55EB83591
345	1FTWF30P75EB83592
346	1FTWF30P05EB83594
347	1FTWF30P25EB83595
348	1FTWF30P45EB83596
349	1FTWF30P65EB83597
350	1FTWF30P85EB83598
351	1FTWF30PX5EB83599
352	1FTWF30P25EB83600
353	1FTWF30P45EB83601
354	1FTWF30P65EB83602
355	1FTWF30P85EB83603
356	1FTWF30PX5EB83604
357	1FTWF30P15EB83605
358	1FTWF30P35EB83606
359	1FTWF30P55EB83607
360	1FTWF30P75EB83608
361	1FTWF30P95EB83609
362	1FTWF30P55EB83610
363	1FTWF30P95EB83612
364	1FTWF30PX5EC01504
365	1FTWF30P15EC01505
366	1FTWF30P35EC01506
367	1FTWF30P55EC01507
368	1FTWF30P75EC01508


No.	VIN
369	1FTWF30P95EC01509
370	1FTWF30P05EC15914
371	1FTWF30P25EC15915
372	1FTWF30P45EC15916
373	1FTWF30P65EC15917
374	1FTWF30P85EC15918
375	1FTWF30PX5EC15919
376	1FTWF30P45EC14331
377	1FTWF30P65EC14332
378	1FTWF30P85EC14333
379	1FTWF30PX5EC14334
380	1FTWF30P15EC14335
381	1FTWF30P35EC14336
382	1FTWF30P65EC15920
383	1FTWF30PX5EB92139
384	1FTWF30P65EB92140
385	1FTWF30P65EC01502
386	1FTWF30P15ED02558
387	1FTWF30P35ED02559
388	1FTWF30PX5ED02560
389	1FTWF30P15ED02561
390	1FTWF30P25ED02567
391	1FTWF30P45ED02568
392	1FTWF30P65ED02569
393	1FTWF30P25ED02570
394	1FTWF31P95EB83558
395	1FTWF31P05EB83559
396	1FTWF31P75EB83560
397	1FTWF31P95EB83561
398	1FTWF31P05EB83562
399	1FTWF31P25EB83563
400	1FTWF31P45EB83564
401	1FTWF31P65EB83565
402	1FTWF31P85EB83566
403	1FTWF31P55EB83640
404	1FTWF31P75EB83641
405	1FTWF31P95EB83642
406	1FTWF31P05EB83643
407	1FTWW30P65EB83549
408_	1FTWW30P25EB83547
409	1FTWW30P45EB83548
410	1FTWW30P25EB83550
411	1FTWW30P45EB83551
412	1FTWW30P65EB83552
413	1FTWW30P85EB83553
414	1FTWW30PX5EB83554

No.	VIN
140.	
415	1FTWW30P15EB83555
416	1FTWW30P35EB83556
417	1FDWW30P05EB83557
418	1FTWW30P05EC01494
419	1FTWW30P25EC01495
420	1FTWX31P75EC24900
421	1FTWX31P95EC24901
422	1FTWX31P05EC24902
423	1FTWX31P25EC24903
424	1FTWX31P45EC24904
425	1FTWX31P65EC24905
426	1FTWX31PX5EC24907
427	1FTWX31P15EC24908
428	1FTWX31P35EC24909
429	1FTSX31P25ED02580




Destination:

SMDA



Waybill:

8772487765



Acct: 805892828 Date: 08/06/2005

Ref:

10WE Routing:

4X/ABH

Weight: 1.0 lbs.

Origin: DTW

Pcs: 1

FR: FORD AUTOMOTIVE SAFETY OF

Tara Brush

330 TOWN CTR

DEARBORN, MI

48126 United States Of America

Ph: (313) 337-1920 Fax:

TO: Nat'l Hwy Trffc Sfty Admin,

David Coleman

400 Seventh St. S.W.

Rm. # 6111

Washington, DC

20590 United States Of America

Ph: (202) 366-9700 Fax:

Description: documents

Fold here. Affix to package using DHL plastic pouch.



I/we have agreed that DHL's standard terms apply to this shipment and limit DHL's liability for loss or damage to US \$ 100. I/we understand that shipment value protection is available on request, for an extra charge. I/we agree to pay all charges if the recipient or third party does not pay. I/we understand that DHL DOES NOT TRANSPORT CASH.

SIGNATURE: Tara Brush

DHL Worldwide Express, Inc., 1200 South Pine Island Rd, Suite 600, Plantation, FL 33324 http://www.dhl.com 1-800-CALL-DHL (in the USA only)



Reprinted

FOR USE BY DHL ORIGIN PROCESSING (Drop Box ID - Additional Charges - Transport Collect Label #)