

Our Ref : 17134
Your Ref : 29367

Date of Report : 25 May 2026
Date Instructed : 22 May 2026

Date of Inspection : 24 May 2026
Date of Accident : 22 May 2026

Instructed By : NATIONWIDE ASSIST LTD
Address : 25 - 39, SMALLHEATH HIGHWAY, BIRMINGHAM, B10 0EU

Insured : MR. S MIAH
Third Party :
Address :

VEHICLE DETAILS

Reg No : BF16FFV
Make : TOYOTA
Model : PRIUS
Body : HATCHBACK
Spec : VVTI BUS ED
Engine CC : 2705
Fuel Type : HYBRID
Chassis No : ///////////////
Mileage : 100000 Miles
Date of Reg : 28 April 2016
Tax Expiry : /////
Doors : 5
Transmission : AUTOMATIC
Colour : SILVER
Audio : AUDIO
Extras : NON APPARENT
Paint : METALLIC

TYRE TREADS (mm)

OSF :
NSF :
OSR :
NSR :
Others :

STATIC CHECKS

Steering : SATISFACTORY
Footbrake : SATISFACTORY
Handbrake : SATISFACTORY
Seatbelts : SATISFACTORY


IMPACT DETAILS

Mechanical :
Body : LIGHT

Inspection Location : WITH CLIENT

Vehicle Status : REPAIRABLE
: IN USE

Pre-Accident Condition of Vehicle : ABOVE AVERAGE
Cause of Damage : ACCIDENT



Repairer : NO ESTIMATES OBTAINED
Labour Rate £ 95.00
Repair Time In Days : 3

Labour £ 950.00
Paint / Materials £ 545.00
Parts £ 175.00
Specialist £ 110.00
Total Exc VAT £ 1780.00
Total Inc VAT £ 2136.00

V.A.T @ 20 % £ 356.00
Provisional Reserve £ 2136.00
Excess £
Vehicle Market Value £ 7000.00

Glass's Retail Value £
Glass's Older Cars Value £

Glass's Trade Value £
Dealer Retail Value £

Average Mileage Of :
Glass's Private Sale Value £

Engineers Valuation Figure £ 7000.00
(Adjustments regarding vehicle age, mileage, date of registration included)

Salvage Value £
Motor Salvage Category :

Recovery Charges £ 0.00
Date Storage Commenced :

Charges Being Incurred : Storage Per Day £

Comments / Repair Notes :

THE ABOVE VEHICLE HAS SUSTAINED LIGHT NEARSIDE REAR IMPACT DAMAGE, NO ESTIMATES WERE RAISED, IN THE ABSENCE OF ESTIMATES, THIS REPORT CONTAINS PROJECTED COSTS BASED UPON THE IMAGES OF THE DAMAGE SUSTAINED IN THE INCIDENT PLEASE DEAL WITH ACCORDINGLY. VALUATION BASED UPON ADVISED MILEAGE. VEHICLE CHECKS MAY REVEAL ADDITIONAL DAMAGE AND INCREASE COSTS ...PROJECTED REPAIR COSTS BASED UPON 10 HRS @ £95 PER HOUR

please note, as you are probably aware Glass guide estimating system has been subject to a cyber attack rendering the system temporary unusable, this is an interim report carried out to keep the system moving and is based upon limited information, note vehicle values are based upon similar vehicles found for sale in the market place

ENGINEER: STEVE PRINT A.M.I.M.I. AQP IA01047



I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

PART REQUIREMENTS

Our Ref : 17134

Your Ref : 29367

Parts Specification	Action
NEAR/SIDE FRONT DOOR SHELL	Repair
NEAR/SIDE FRONT DOOR MOULDINGS	Repair
NEAR/SIDE FRONT TYRE	Replace With New
NEAR/SIDE FRONT ROAD WHEEL	Repair
NEAR/SIDE REAR HUB	Check
NEAR/SIDE REAR STRUT	Check
NEAR/SIDE REAR DOOR SHELL	Repair
NEAR/SIDE REAR DOOR MOULDINGS	Repair
NEAR/SIDE REAR QUARTER PANEL	Repair
NEAR/SIDE REAR INNER QUARTER PANEL	Repair
NEAR/SIDE REAR WHEEL ARCH	Repair
MOULDINGS	Replace With New
PAINT AND PROCESS MATERIALS	Replace With New
BLEND IN SURROUNDING PANELS	Repair
~~~~~ SPECIALIST ~~~~~	Specialist
GEOMETRY	Specialist
JOB ALLOWANCE	Specialist
EPA CHARGE	Specialist
VALET	Specialist

I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not.  
Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

**Instructed by :**

NATIONWIDE ASSIST LTD  
25 - 39, SMALLHEATH HIGHWAY, BIRMINGHAM, B10 0EU

## INVOICE / FEE NOTE

**Our Ref** : 17134  
**Your Ref** : 29367  
  
**Date of Inspection** : 24 May 2026  
**Date of Report** : 25 May 2026  
  
**Vehicle** : TOYOTA PRIUS VVTI BUS ED  
**Reg No** : BF16FFV  
**Date of Reg** : 28 April 2016

**Client** : MR. S MIAH

**Engineers Report Fee :** £ 85.00

**Any additional charge details :**

**TOTAL** £ 85.00