SkiGear Co. 1661 Mesa Drive Las Vegas, Nevada 123-555-5555

## **EQUIPMENT INSPECTION**

SERIAL NUMBER	/ INSPECTION GRADE	
SGMM-12345	FAIL	

## INSPECTION SUMMARY

During the inspection of the injection molder, an issue was detected with a specific part of the machine. The nozzle was found to be clogged, resulting in the production of defective parts. To address the problem, the technician thoroughly examined the nozzle and discovered residual material obstructing its flow. Swiftly taking action, the technician meticulously cleaned the nozzle, restoring its functionality and allowing the machine to resume production of high-quality parts. In order to prevent future occurrences of such failures, the technician emphasized the importance of regular maintenance for the machine. Overall, the timely identification and resolution of the issue ensured that production could continue without further delays or compromised output.

Injection Unit	Defective X
Mold Clamping Unit	(100)
Hydraulic System	Gurod
Temperature Control System	Good
Ejector System	Good
Lubrication System	Good
Safety Devices	Good
Control Software	Good

Emily Johnson 2022-06-01
Inspected by Date