SkiGear Co. 1661 Mesa Drive Las Vegas, Nevada 123-555-5555

EQUIPMENT INSPECTION

MACHINE	SERIAL NUMBER	INSPECTION GRADE
Injection Molder	SGMM-12345	(FAIL

INSPECTION SUMMARY

During the inspection of the injection molder, it was discovered that the machine was producing defective parts due to a clogged nozzle. The technician investigated the issue and found that there was residual material buildup inside the nozzle. After cleaning the nozzle, the machine resumed production of good quality parts. To avoid similar issues in the future, the technician advised implementing a regular maintenance schedule. Overall, swift action was taken to identify and resolve the problem, ensuring that production could continue without further interruptions.

Injection Unit	Defective X
Mold Clamping Unit	Good
Hydraulic System	Good
Temperature Control System	Good
Ejector System	Gred
Lubrication System	Good
Safety Devices	Good
Control Software	Gand

Emily Johnson

2022-12-01

Inspected by

Date