SkiGear Co. 1661 Mesa Drive Las Vegas, Nevada 123-555-5555

EQUIPMENT INSPECTION

MACHINE	SERIAL NUMBER	INSPECTION GRADE	1
Injection Molder	SGMM-12345	FAIL	

INSPECTION SUMMARY

During the inspection of the injection molder, it was observed that one of the parts on the machine was failing. Specifically, the nozzle seemed to be clogged, which was causing the production of defective parts. The technician examined the nozzle and found that it had some residual material stuck inside. They cleaned the nozzle thoroughly, and the machine resumed production of good quality parts. The technician recommended regular maintenance of the machine to prevent such failures in the future. Overall, prompt action was taken to identify and rectify the issue, ensuring that production could resume without further delays.

Injection Unit	Defactive X
Mold Clamping Unit	G7503 V
Hydraulic System	Good V
Temperature Control System	G200d
Ejector System	Good
Lubrication System	Good
Safety Devices	Good
Control Software	(200-

Emily Johnson Inspected by

<u>2023 - 03 - 01</u> Date