SkiGear Co. 1661 Mesa Drive Las Vegas, Nevada 123-555-5555

EQUIPMENT INSPECTION

| SERIAL NUMBER | INSPECTION GRADE | |
|---------------|------------------|--|
| SGMM-12345 | FAIL | |
| | | Delin Livering Liveri |

INSPECTION SUMMARY

While inspecting the injection molder, a notable issue was discovered with one of its parts. Specifically, the technician identified a clogged nozzle, leading to the production of defective parts. Upon closer examination, residual material was found lodged inside the nozzle. The technician promptly cleaned the nozzle, restoring the machine's ability to produce highquality parts. In order to prevent similar failures in the future, regular maintenance of the machine was strongly advised. Overall, swift action was taken to identify and resolve the problem, enabling uninterrupted production to resume without any further delays.

| Injection Unit | Defective X |
|----------------------------|-------------|
| Mold Clamping Unit | Good |
| Hydraulic System | Good |
| Temperature Control System | Good |
| Ejector System | Grood |
| Lubrication System | Good |
| Safety Devices | Good |
| Control Software | Good |

2012-09-01 Date