
HE_0
HE_30
HE_60
Fraction of all points failed with plastic strain ≤ value
Plastic strain at failure
0.0
0.1
0.2
0.3
0.4
0.5