18th May

Friday, 15 May 2026 11:35 am

Executive Summary

Validation	Highlights	Comments	Overall Status & Risks
Skyline RC (RG2) validation	• RG2 validation completed (100% completed) • All Rounds completed. Triaging & Supporting R&D is ongoing • DUNE-311046 - Sunspear Hang in 5th hour CD. Only reproducible in one unit due to Mem Assert • FW Team requested to raise new defect DUNE-314838 as another issue found in core dump • Failure mode of both DUNE-311046 and DUNE-314838 is memory leak. Root cause is unknown but customer impact is low	HPXAPPS-56024 - HPx Windows Blank screen issue. (HPXAPPS-56215 as well) Not reproducible at the moment. Monitoring closely. DUNE-311046 • Not reproducible in good unit. Only reproducible in faulty unit. • FW Team to provide answers on why is this still reproducible with one unit - highlighted that this issue would still be reproducible on all units if they are stress tested longer. • Working closely with FW team to find the root cause. • Program Team is reaching to an agreement to defer this defect provided that the root cause has been found. ○ Update : FW Team has announced defect has been deferred to BR1.X.	🟡 Root cause for DUNE-311046 and DUNE-314838 needs to be found.
Leo WL E2E validation	• 3 Rounds Validation Completed • All Round completed except CD, MM print & MM Scan blocked due to HPXAPPS-56024 - defect closed and marked as Fix • ESP still observes blank screen issue after fix • DUNE-307211 - Leo WL stuck in Processing during the CD 5th hour test - Defect Closed as issue not seen	HPXAPPS-56024 - HPx Windows Blank screen issue. (HPXAPPS-56215 as well) - issue still seen. (reproducible on 2 out of 3 PC) DUNE-307211, Not reproducible at the moment. Monitoring closely. New Defect seen : APPWIN-3531	🟡 Though ESP Validation has been completed for Leo, HPXAPPS-56024 issue is still seen. If the issue is not fixed this issue will impact ESP Validation on RC Firmware
Pro RPI 1.1 Validation	• Flowers 3 out of 3 CD run completed • Received Pro RPI new FW build. Scheduled Pro RPI 1x CD run for this week.	No issues seen. Stable.	🟢
Hulk VR1.12	3 out 3 Contention Duration Runs completed - All 3 runs Fail	Defect raised at [SRFWBUG-22801] Hulk UI hang during 2nd hour when running Contention Test - HP-Jira.	🟡 RC - 22nd May ; Quality Risk if defect not fixed.

ESP Program Validation Results

ProRPI - Flowers (Extra Runs Requested by Len)

Test Date	Title	Status	Firmware Version
13th May	Cherry CD 1st run	Pass	6.28.1.103
13th May	Lotus CD 1st Run	Pass	6.28.1.103
14th May	Cherry CD 2nd Run	Pass	6.28.1.103
14th May	Lotus CD 2nd Run	Pass	6.28.1.103
15th May	Cherry CD 3rd Run	Pass	6.28.1.103
15th May	Lotus CD 3rd Run	Pass	6.28.1.103
18th May	Cherry CD	In Progress	6.28.3.19
18th May	Lotus CD	In Progress	6.28.3.19
18th May	Euthenia CD	In Progress	6.28.3.19
18th May	Selene CD	In Progress	6.28.3.19
19th May	Zelus CD	In Progress	6.28.3.19
19th May	Ulysses CD	In Progress	6.28.3.19

- To execute three CD run when the next FW build is released.

Skyline

Skyline Test Suites RG2		**Round 1**				**Round 2**			
		Greenfield		***Sunspear***		***Greenfield***		***Sunspear***	
Contention Duration with HPx		Windows	Pass	Windows	Fail by HPXAPPS-56215	iOS	Pass	Android	Pass
		iOS	Pass	Android	Pass with Defect DUNE-311046	iOS	Pass	Android	Pass
		iOS	Pass	Android	Pass with Defect DUNE-311046	iOS	Pass	Android	Fail by DUNE-311046
Memory Monitoring	*PrintHPx*	Windows	Pass	Windows	Fail by HPXAPPS-56215	Windows	Pass	Android	Pass
	Scan	NA		Windows	Pass	NA		Windows	Pass
	EWS	Windows	Pass	Windows	Pass	Windows	Pass	Windows	Pass
	Copy	NA		Windows	Pass	NA		Windows	Fail by DUNE-311995
	UI	Windows	Pass	Windows	Pass	Windows	Pass	Windows	Pass
	Sleep/Wake	iOS	Pass	Mac	Pass	NA		NA	

Skyline Additional Runs	**OS**	**SKU**	**Result**	**Remark**
Contention Duration	Mac	Greenfield	Pass	Retest, issue not seen
MM Print	Android	Greenfield	Pass	
Contention Duration	Android	Sunspear	Pass	
Contention Duration	Mac	Sunspear	Pass	
MM Copy	-	Sunspear	Pass	Retest - issue not seen
Contention Duration	Android	Sunspear	Pass	Retest, issue not seen
Contention Duration	Android	Sunspear	Fail	Retest with faulty unit
Contention Duration	Android	Sunspear	Fail	Retest with faulty unit
Contention Duration	Android	Sunspear	Fail	Retest with faulty unit

2 Active Defects

1. [DUNE-311046] [ESP] SunspearPlusWL hang during contention test. - HP-Jira
   - Team liaising with FW engineer to reproduce and capture logs
2. [DUNE-314838] SunspearPlus Memory assert encountered during Contention and Memory test - HP-Jira
   - Newly raised defect linked to DUNE-311046

Closed Defects

1. [DUNE-311995] [ESP] SunspearPlus assert on 5th hour when running Memory monitor UI Copy test - HP-Jira - Closed as duplicate and followed under DUNE-311046
2. [DUNE-312547] [ESP] SunspearPlus assert on 2nd hour during running Contention test - HP-Jira - Closed as duplicate and followed under DUNE-311046
3. [DUNE-310433] [Skyline printer]: During printer onboarding with the HPX Windows app, steps 2 and 3 display "Unable to configure the printer" and "Unable to join the network" errors for all APs, regardless of configuration. - HP-Jira
4. [HPXAPPS-56215] A blank screen is observed when HPX is launched - HP-Jira

Leo

Leo Test Suites	**Round 1**	**Round 2**	**Round 3**
Total: 21 test runs	*Leo WL - E2E*		*Leo WL - RG1*
Contention Duration	Fail	Pass	Fail Windows + Mac ***Windows HPx prompted to install drivers during run, even though the drivers are already installed.*** ***Scheduled on 11/05/2026 - CD Android +***

				Windows
Memory Monitoring	*Print*	Pass	Pass	Fail Windows ***Blank screen observed during test.*** ***Re-test on different PC to check if issue is still reproducible.***
	Scan	Pass	Pass	Fail Windows ***Re-tested using latest Windows HPx build (56.52617.5769.0) . Install driver issue not seen, continue to monitor on MM Print. Blank screen still seen, 4 times out of the whole run.***
	EWS	Pass	Pass	Pass
	Copy	Pass	Pass	Pass
	UI	Pass	Pass	Pass
	Sleep/Wake	NA	NA	**Pass**

1. [DUNE-307211] Leo stuck in processing state in 5th hour when performing contention test - HP-Jira
   - Occurred in Windows HPx 1 time; Unable to reproduce
   - Defect Closed
2. [HPXAPPS-56215] [BLOCK] A blank screen is observed when the HPX app is launched. - HP-Jira : Only for HPx Windows significantly now
   - Issue still being seen
3. [DUNE-308195] Leo scan unsuccessful when there is print job ongoing - HP-Jira : Closed Defect
   - Message prompts print job fail/ scan unsuccessful
   - Behavior difference between Skyline and Leo where Skyline Sunspear is able to support this but not Leo.
     - Sunspear able to handle scan job during print whereas Leo doesn't; Error message "Scan unsuccessful is received for Leo
       - Raised to Leo TME for a possibility of implementing a better message for customers

       Clipchamp
4. [APPWIN-3531] [ESP] "Install driver to print" prompted in HPX window intermittent when click on Print photos or Print documents - HP-Jira

CPE - HULK (before RC Contention Duration Validation)

Test Date	Title	Status	Firmware Version	Defect ID
13th May	Hulk CD 1st run	Fail	002.2619A	SRFWBUG-22801
14th May	Hulk CD 2nd run	Fail	002.2619A	SRFWBUG-22801
15th May	Hulk CD 3rd run	Fail	002.2619A	SRFWBUG-22801

- Investigating if this issue occurs in older RC FW.