
扳手轴孔尺寸

共 / 真 第 / 頁 編号 811-6 工厂标准 GONGCHANG BIAOZHUN 根据 JB/GQ112-80 扳手轴 和 扳手孔 代替 秦川机床厂 R 類 别 一般标准

		12	
S	()		\Box
L	4		5





				d ₃	L ₃		d٠	La		d,		5	5
			轴 (h/3)	基本尺寸	孙轴	转 (hB)	基本寸	礼轴	\$ ф (hl3)	基本尺寸	差(1/2)	偏 (h(3)	本す
	+ 1				3.5	0	4	4.2		4	+0.02	-8.14	3
	3	1			4.6	-0.18	5.1	5,7	-0./8	5			4
					5.8		6.5	7.1		6	+0.15	- D. / AL	5
		-			6.4	0	7	7.8		7	+0.03		5.5
				6.9	-0,22	7.6	8.5	-0.22	8	- 1	1	6	
	-				8.1	1 1	8.6	9.9	0.22	10			7
			9759		9.2		9.6	11.3		10	+0.19	-0.22	8
			-	_	10.4		11.6	12.7			10.04	1	9
	- 1				11.5	ا ما	/2.6	14.1		12		1	0
150					12.7	-0.27	/3.6	15.6	-0.27				11
	7.17				13.9		15.6	17.0		14	+0,23	-0.27	12
					16.2	1 1	/7.5	19.8	1	16	+0.05	-0.21	14
4					19.6		21.5	24.0		20		1	17
-	-				21.9	-0.33	24.5	26.9	0	22			19
	-	_	-	23.8	25.4		27.5	31.1	-0.33	25	+0,27	1.	22
			-0.43	26	27.7		32	33,9	1	28		-0,33	24
			-	29.1	31.2		36	38.2		32	+0.06	1	27
-/-			-0.39	32.5	34.6	-0.39	40	424	0.00	36	1	1	30
				34.6	37.0		42	45,3	-0.39	40			32
-				39	41.6	1 1	48	50,9		44	+0.33	0	36
				44.4	47.3		54	58.0	1	48		-0.39	41
-	-			49.8	53.1		60	65.1		54	+0.08		46
7.5	1.		-	54./		-0.46	65	70.7		60		1	50
-	0.7		-	59.5	63.5		72	72.8	-0.46	66			55
	-		8 -0.33 / 5 6 -0.39 4 8 / 5 -0.46 3 7 -0.46	-0.46		69.3		72		1	60		
		-		70.3	75.1		85	91.9	1 I	78	+1.40		65
			-		80.8	0	92			84	+0.10	-0.46	70
		_	-	75.7	86.6	-0.46	98	99.0	-0,46	90		-	75
	-		-0.46	86.6	92.4	-	/05	113.1	4 6	96		+	80

附 it: ^① 切削工具用方头的尺寸可不受本规格限制。 D L₂ = <u>S</u> , L₃ = <u>S</u> sin 60°