Show of Hands

Outline

:1C HCK!

- Safety Tips
- Overview of Terminology and Process
- Gather parts, sand board
- Practice
- Screenprint solder
- Place
- Reflow