## Process

- Sand board
- Obtain parts (will describe each)
- Practice placing three parts
- Screen print on solder paste
- Place parts for realz
- Heat on hot plate: solder reflows
- Program bootloader

## 12 parts total, 8 different parts

