



1 GENERAL INFORMATION

DESIGNERS

Jayce Cheng
Pablo Quijano Velasco
Leong Chang Jie
Eleen Koay

INSTITUTION

Institute of Materials Research and Engineering (IMRE),
Agency for Science, Technology and Research (A*STAR),
Singapore

2 DESCRIPTION


This is the assembly guide for the Qubot Gantry module.
Version: V4
*Refer to separate manual for microcontroller and wiring.
*Utility frame not included

3 SKILLS & RESOURCES


Access to FDM 3D printing
Access to metal CNC milling
Access to acrylic laser cutting
Heat insert









Required
Optional
Optional
Required

4 TOOLS



5 MODEL






Hex countersunk

M3×06 **2x**
M3×10 **4x**
M3×14 **4x**

M4×08 **12x**
M4×10 **2x**
M4×14 **4x**

M5×10 **4x**
M6×10 **4x**




Hex button

M2×08 **6x**
M2.5×06 **2x**
M2.5×14 **4x**


M3×08 **5x**
M3×12 **4x**

M5×08 **22x**
M6×10 **2x**



Drop-in T-nut 2020

M3 **1x**
M4 **16x**
M5 **22x**



Socket

M3×06 **12x**
M3×12 **4x**
M3×25 **8x**
M5×20 **6x**

Knurled heat insert



M2×L3×OD3.2 **6x**
M2.5×L3×OD3.5 **2x**
M3×L3×OD4.5 **21x**


Dome nut



M3 **1x**




X and Z endstop mount




2x ↑

Z-axis mount




1x ↗

Y endstop trigger




1x ↗

Y cable chain mount




1x ↑

Y endstop mount




1x ↗

Z platform




1x ↗

Z cable chain mount




1x ↗

Z casing




1x ↓

Electronic casing back




1x ↗

Electronic casing front




1x ↗

Electronic casing base




1x ↗

Cable track



1x ↓

L fore casing













1x ↓

R fore casing




1x ↓






1 HEAT INSERT




2 ASSEMBLY


1




2




3




4




5




Left gantry (y1-axis)




6




7




8




9




10





11




12






13




Crossbar (x-axis)






Baseplate with gantries


15




16




17




18




19




20





21




All axes assembled




Refer to Utility frame.step
*Customize utility frame per
your mounting setup




23




24



25



26




27



Refer to microcontroller and wiring manual


a

Duet 3 Mini 5+ Wifi
\$\$




b

Arduino Nano + DRV8825
\$



28



29

Full assembly

