
Ground Level
W
E
Area of significant difficulty
due to bridge structure interference and deep holes.
Measurements in this area are indicative only.

DATUM 80.00

| | | |