	M13M1	4 Mig	1b,2 M1	Lim M6	b 3 M7	M-jm	Ы4 <sub>1</sub>	Lim M2	₩ <u>5</u>	Lim M4	b 6 M5	Lim M8	16 To	Lim M15	b 8 М16
LC 1 Z	-1 <b>5.</b> 7 <mark>43</mark> .	8 -19.7	24.6	1.4	-3.8	1.2	-9.7	9.1	12.4	8.3	17.7	8.8	14.2	-9.9	11.5
LC 2 Z	8.7 -41	.9 44.1	3.9	17.0	35.6	1.9	17.6	6.6	1.2	-8.4	4.2	<b>-5.</b> 3	10.4	-3.8	4.3
LC 3 Z	0.5 -20	.8-23.4	-40.5	42.0	-19.3	18.5	36.5	- <b>13</b> .1	-4.3	1.1	- <b>5</b> .6	7.8	1.3	4.3	1.5
LC 4 Z	2.8 14.	7 -2.0	11.6	22.8	-14.8	-22.3	-51.2	-4.8	-9.7	-3.6	- <b>17.</b> 3	-8.2	-26.4	6.1	- <b>17.</b> 8
LC 5 Z	- <b>51</b> 6 1 <mark>4</mark> .	7 9.2	21.1	6.3	14.3	10.6	11.8	28.1	44.3	-28.9	20.8	3.7	-4.0	-4.7	-9.9
LC 6 Z	-1•.7 0•7	7 -7.3	0.1	-1.6	11.7	8.0	7.1	-27.9	-36.6	49.3	16.7	16.3	39.9	1.6	17.6
LC 7 Z	5.2 - <b>5</b>	9 0:3	-8.6	10.9	-4.8	-3.8	-1.7	-1.1	-15.7	-27.8	38.6	-32.0	-7.9	-16.5	47.0
LC 8 Z	8.8 -11	.4-10.7	'-15.3	-5.6 ·	-22.4	-7.1	-18.2	0.3	9.4	1.2	3.6	16.4	-26.7	17.1	-56.0