	LC 1	LC 2	LC 3	LC 4
Motor 1	0.18	0.22	0.39	0.33
Motor 2	0.29	0.33	0.44	0.37
Motor 3	0.21	0.16	0.24	0.30
Motor 4	0.32	0.24	0.28	0.44
Motor 5	0.39	0.28	0.29	0.31
Motor 6	0.40	0.23	0.17	0.28
Motor 7	0.33	0.48	0.32	0.31
Motor 8	0.33	0.46	0.34	0.25