

$$\chi_{Am} = \chi_{1Am} = \frac{1.1 \cdot 35}{300} = 4.5$$

$$V_{OAM} = 1.135^2 \cdot \left(\frac{3}{180} - \frac{2}{300}\right) = 13.47$$

$$|u_1| = |x_3| + |x_1| + |x_3|$$
Nedjelja
15


$$\frac{\sqrt{3} \cdot 1.1 \cdot 35}{3.38 + 3.38 + 3.76} = 6.3 \text{ UA}$$

18.00

 $V_{0} = 3V_{0} = 1.98 \Omega$   $V_{0} = 3V_{0} = 1.98 \Omega$   $V_{0} = 3V_{0} = 1.98 \Omega$ 

Vd=X1=046 X0=13852

 $Y_1 = Y_0 = 0.000 \cdot \frac{20^2}{20} = 1.60$  $V_0 = 2 \times d = 2.1.6 = 3.20$ 



STROJOPROMET-ZAGREB d.o.o. Prigornica 2 • Podsused, 10090 Zagreb • Tel.: 01 3440 222 • Fox: 01 3440