



Bilde 1 – Signal som forventet




Bilde 2 - Signal med litt sjegg




Bilde 3 – For stor båndbredde – Manglene jammesignal



Bilde 4 - For stor båndbredde – Manglene jammesignal



Bilde 5 –Stor TW



Bilde 6 – Lav TW

```
[00:00:03.939921819] Setting device timestamp to 0...

[UANNING] [0/Radio#0] Attempting to set tick rate to 0. Skipping.

Setting TX spp to 2000
[00:00:03.944291372] Testing transmit rate 200.0000000 Msps on 1 channels
[00:00:14.195561334] Benchmark complete.

Benchmark rate summary:
Num received samples: 0
Num dropped samples: 0
Num overruns detected: 0
Num transmitted samples: 2049712000
Num sequence errors (Tx): 0
Num sequence errors (Rx): 0
Num underruns detected: 0
Num late commands: 0
Num timeouts (Tx): 0
Num timeouts (Tx): 0
Num timeouts (Rx): 0

Done!

entigenti-nc:/upr/local/lib/uhd/examples$ ./benchmark_rate --args master_clock_rate=200e6 --tx_rate 200e6
```

Bilde 7 - Benchmark av 200 MS/s