MobileDeviceService

Personal informations : Martin Banas Zilina martinbanass@gmail.com 0908123456
Registration Date : 2014-04-06 01:02:54.0
Fault : Prasknuty display, potreba vymenit, obliaty reproduktor nehra
IMEI : 2354123577
Device type : Lumia 1020 NOKIA
Repair report : vymenene dotykove sklo , vymeneny reproduktor
Repair costs : 45.50€
Send back date : 2014-04-06 04:41:31.0